



Inspection report

Date: 6/16/2022	Work Order:	Weather: Dry	Surveyed By: Steven Bucklin	Certificate Number: U-0819-70306510	Pipe Segment Ref.: MH050310-MH050311
Year laid:	Pre-cleaning: Light Cleaning	Direction: Downstream	Pipe Joint Length:	Total Length:	Length Surveyed:

City: Superior	Drainage Area:	Upstream MH: MH050311
Street: HILL	Media Label: 1115	Up Rim to Invert: 0.0
Location Code: Local rural streets with light traffic	Flow Control: Lift Station	Downstream MH: MH050310
Location Details:	Sheet Number:	Down Rim to Invert: 0.0
Pipe shape: Circular	Sewer Use: Sanitary Sewage Pipe	Total gallons used: 0.0
Pipe size: 15	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method: None	Owner: City of Superior	

Additional Info:

1:2882	Distance	Code	Observation	Counter	Photo	Grade
MH050311						
	0.0	AMH	Manhole / MH050311	00:00:01	MH050310 -MH05031 1_1c6e48d	
	0.0	MWL	Water Level, 15% of the vertical dimension	00:01:17	MH050310 -MH05031 1_f3b9fcac	
	1.5	S01	SAP	00:02:09	MH050310 -MH05031 1_6ec23e4	
	15.4	SAM	Surface Damage Aggregate Missing from 9 o'clock to 1 o'clock, within 8 inch	00:04:29	MH050310 -MH05031 1_f8c294a	S4
	23.4	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 9 o'clock to 3 o'clock, within 8 inch	00:05:37	MH050310 -MH05031 1_f578340	M2
	35.5	S02	DAE	00:07:45	MH050310 -MH05031 1_72fbd13	
	43.6	JAM	Joint Angular Medium	00:08:58	MH050310 -MH05031 1_9aada9	S3
	70.2	SRV	Surface Damage Reinforcement Visible from 12 o'clock to 2 o'clock, within 8 inch	00:11:07	MH050310 -MH05031 1_4a0b09	S4
	170.8	SRV	Surface Damage Reinforcement Visible from 2 o'clock to 3 o'clock	00:17:10	MH050310 -MH05031 1_77a7bd	S4
	237.3	ISGT	Intruding Sealing Material Grout, 5% of cross sectional area from 6 o'clock to 9 o'clock	00:21:19	MH050310 -MH05031 1_d52c9cf	M2
	286.7	SRP	Surface Damage Reinforcement Projecting from 12 o'clock to 3 o'clock	00:26:56	MH050310 -MH05031 1_ef7a492	S5
	305.0	B	Broken from 10 o'clock to 12 o'clock	00:28:50	MH050310 -MH05031 1_8a838d	S4
	305.6	TBI	Tap Break-In Intruding at 11 o'clock, dia/height: 4inch, intruding: 1inch / CONSTANTLY DRIPPING WATER.	00:29:12	MH050310 -MH05031 1_e3d06e	M2
	342.4	SRV	Surface Damage Reinforcement Visible from 10 o'clock to 2 o'clock, within 8 inch	00:32:07	MH050310 -MH05031 1_df2f6a1	S4
	368.4	S03	SRV	00:34:07	MH050310 -MH05031 1_045467	



Inspection report

Date: 6/16/2022	Work Order:	Weather: Dry	Surveyed By: Steven Bucklin	Certificate Number: U-0819-70306510	Pipe Segment Ref.: MH050310-MH050311
Year laid:	Pre-cleaning: Light Cleaning	Direction: Downstream	Pipe Joint Length:	Total Length:	Length Surveyed:

1:2882	Distance	Code	Observation	Counter	Photo	Grade
	395.1	F01	SAP	00:35:43	MH050310 -MH05031 1_842924	S3
	395.1	F02	DAE	00:35:52	MH050310 -MH05031 1_64dded	M2
	395.1	F03	SRV	00:36:01	MH050310 -MH05031 1_abdd80	S4
	396.8	AMH	Manhole / MH050310	00:39:29	MH050310 -MH05031 1_c76574e	

QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
514A	2N00	514A	285.0	150.0	435.0	3.1	2.0	2.6