



Inspection report

Date: 6/16/2022	Work Order:	Weather: Dry	Surveyed By: Steven Bucklin	Certificate Number: U-0819-70306510	Pipe Segment Ref.: MH050311-MH050312
Year laid:	Pre-cleaning: Light Cleaning	Direction: Upstream	Pipe Joint Length:	Total Length:	Length Surveyed:

City: Superior	Drainage Area:	Upstream MH: MH050312
Street: HILL	Media Label: 1115	Up Rim to Invert: 0.0
Location Code: Local rural streets with light traffic	Flow Control: Lift Station	Downstream MH: MH050311
Location Details:	Sheet Number:	Down Rim to Invert: 0.0
Pipe shape: Circular	Sewer Use: Sanitary Sewage Pipe	Total gallons used: 0.0
Pipe size: 15	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method: None	Owner: City of Superior	

Additional Info:

1:2632	Distance	Code	Observation	Counter	Photo	Grade
MH050311	0.0	AMH	Manhole / MH050311	00:00:00	MH050311 -MH05031 2_24d0a5	
	0.0	MWL	Water Level, 5% of the vertical dimension	00:01:12	MH050311 -MH05031 2_067f3cb	
	1.5	S01				
	56.1	B	Broken from 10 o'clock to 11 o'clock, within 8 inch	00:06:41	MH050311 -MH05031 2_e1d3b1f	S4
	56.4	TBI	Tap Break-In Intruding at 11 o'clock, dia/height: 4inch, intruding: 1inch / ACTIVITY.	00:06:59	MH050311 -MH05031 2_7db782	M2
	87.8	SRV	Surface Damage Reinforcement Visible at 12 o'clock, within 8 inch	00:09:13	MH050311 -MH05031 2_379617	S4
	204.7	SAM	Surface Damage Aggregate Missing from 8 o'clock to 12 o'clock, within 8 inch	00:15:58	MH050311 -MH05031 2_b9fd4ba	S4
	220.7	IWJ	Infiltration Weeper Joint from 11 o'clock to 1 o'clock, within 8 inch	00:19:34	MH050311 -MH05031 2_6feff1d2	M2
	220.7	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 9 o'clock to 3 o'clock, within 8 inch	00:19:47	MH050311 -MH05031 2_acf0780	M2
	225.0	IWJ	Infiltration Weeper Joint from 12 o'clock to 1 o'clock, within 8 inch	00:17:56	MH050311 -MH05031 2_cfa1a6b	M2
	225.0	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 11 o'clock to 3 o'clock, within 8 inch	00:18:39	MH050311 -MH05031 2_3147ee	M2
	277.4	SAM	Surface Damage Aggregate Missing from 8 o'clock to 1 o'clock, within 8 inch	00:23:30	MH050311 -MH05031 2_7f720b5	S4
	281.3	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 10 o'clock to 12 o'clock, within 8 inch	00:24:20	MH050311 -MH05031 2_4d7b2cf	M2
	284.8	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 4 o'clock to 5 o'clock, within 8 inch	00:25:05	MH050311 -MH05031 2_62a70fe	M2
	317.5	ISJ	Infiltration Stain Joint from 9 o'clock to 10 o'clock, within 8 inch	00:27:14	MH050311 -MH05031 2_3c95abf	M1
	348.4	B	Broken from 1 o'clock to 3 o'clock, within 8 inch	00:29:30	MH050311 -MH05031 2_c283075	S4



Inspection report

Date: 6/16/2022	Work Order:	Weather: Dry	Surveyed By: Steven Bucklin	Certificate Number: U-0819-70306510	Pipe Segment Ref.: MH050311-MH050312
Year laid:	Pre-cleaning: Light Cleaning	Direction: Upstream	Pipe Joint Length:	Total Length:	Length Surveyed:

	Distance	Code	Observation	Counter	Photo	Grade
	349.1	TBI	Tap Break-In Intruding at 2 o'clock, dia/height: 6inch, intruding: 2inch, within 8 inch / CONSTANTLY RUNNING WATER.	00:29:54	MH050311 -MH05031 2_3d99db	M3
	349.8	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 12 o'clock to 3 o'clock, within 8 inch	00:30:31	MH050311 -MH05031 2_9061a1	M2
	349.8	IDJ	Infiltration Dripper Joint at 1 o'clock, within 8 inch	00:30:41	MH050311 -MH05031 2_5638b2	M3
	397.2	F01 SAP	Surface Damage Aggregate Projecting from 9 o'clock to 3 o'clock, within 8 inch, Finish	00:33:44	MH050311 -MH05031 2_b7823b	S3
	397.2	AMH	Manhole / MH050312	00:36:05	MH050311 -MH05031 2_a5847c2	

QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
453N	3228	453O	257.0	23.0	280.0	3.1	2.1	2.9