



## Inspection report

Date: <b>6/16/2022</b>	Work Order:	Weather: <b>Dry</b>	Surveyed By: <b>Steven Bucklin</b>	Certificate Number: <b>U-0819-70306510</b>	Pipe Segment Ref.: <b>MH050316-MH05316A</b>
Year laid:	Pre-cleaning: <b>Light Cleaning</b>	Direction: <b>Upstream</b>	Pipe Joint Length:	Total Length:	Length Surveyed:

City: <b>Superior</b>	Drainage Area:	Upstream MH: <b>MH05316A</b>
Street: <b>HILL</b>	Media Label: <b>1115</b>	Up Rim to Invert: <b>0.0</b>
Location Code: <b>Local rural streets with light traffic</b>	Flow Control: <b>Lift Station</b>	Downstream MH: <b>MH050316</b>
Location Details:	Sheet Number:	Down Rim to Invert: <b>0.0</b>
Pipe shape: <b>Circular</b>	Sewer Use: <b>Sanitary Sewage Pipe</b>	Total gallons used: <b>0.0</b>
Pipe size: <b>15</b>	Sewer Category: <b>SEC</b>	Joints passed: <b>0</b>
Pipe material: <b>Reinforced Concrete Pipe</b>	Purpose: <b>Routine Assessment</b>	Joints failed: <b>0</b>
Lining Method: <b>None</b>	Owner: <b>City of Superior</b>	



Additional Info:

1:1670	Distance	Code	Observation	Counter	Photo	Grade
	0.0	AMH	Manhole / MH050316	00:00:01	MH050316 -MH05316 A_4ab2f9a	
	0.0	MWL	Water Level, 10% of the vertical dimension	00:02:02	MH050316 -MH05316 A_1e9c30	
	3.1	B	Broken from 11 o'clock to 2 o'clock, within 8 inch	00:02:35	MH050316 -MH05316 A_2982f2f	S4
	3.1	RFJ	Roots Fine Joint from 9 o'clock to 3 o'clock, within 8 inch	00:02:46	MH050316 -MH05316 A_4ee39e	M1
	3.4	S01	SAP	00:03:24	MH050316 -MH05316 A_53c1a5	
	11.1	S02	RFJ	00:04:48	MH050316 -MH05316 A_51d7c7	
	23.4	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 9 o'clock to 3 o'clock, within 8 inch	00:06:19	MH050316 -MH05316 A_d02d9d	M2
	67.7	SAM	Surface Damage Aggregate Missing from 9 o'clock to 12 o'clock, within 8 inch	00:08:59	MH050316 -MH05316 A_15d214	S4
	71.8	SAM	Surface Damage Aggregate Missing from 11 o'clock to 1 o'clock, within 8 inch	00:09:54	MH050316 -MH05316 A_8531f00	S4
	107.7	IWJ	Infiltration Weeper Joint from 11 o'clock to 1 o'clock, within 8 inch	00:12:05	MH050316 -MH05316 A_c0e912	M2
	168.5	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 9 o'clock to 3 o'clock, within 8 inch	00:16:25	MH050316 -MH05316 A_2bdd33	M2
	172.5	IWJ	Infiltration Weeper Joint from 11 o'clock to 1 o'clock, within 8 inch	00:17:01	MH050316 -MH05316 A_c240a3	M2
	188.6	S03	DAE	00:18:40	MH050316 -MH05316 A_79f4693	
	220.2	F01	SAP	00:20:42	MH050316 -MH05316 A_b8255a	S3
	220.2	F02	RFJ	00:20:50	MH050316 -MH05316 A_85c315	M1
	220.2	F03	DAE	00:20:59	MH050316 -MH05316 A_47ae92	M2



## Inspection report

Date: <b>6/16/2022</b>	Work Order:	Weather: <b>Dry</b>	Surveyed By: <b>Steven Bucklin</b>	Certificate Number: <b>U-0819-70306510</b>	Pipe Segment Ref.: <b>MH050316-MH05316A</b>
Year laid:	Pre-cleaning: <b>Light Cleaning</b>	Direction: <b>Upstream</b>	Pipe Joint Length:	Total Length:	Length Surveyed:

1:1670	Distance	Code	Observation	Counter	Photo	Grade		
	222.3	AMH	Manhole / MH05316A	00:23:47	MH050316 -MH05316 A_6bd6ce			
 <b>MH05316A</b>								
QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
433G	2A1G	433G	141.0	63.0	204.0	3.1	1.2	2.1