

Pipe Televising Report

Televised by: Infralick
Date Televised: 12-16-98 Tape #: 4 0:09:11
Weather Condition 0:19:59

Precipitation: None Light Heavy Temperature: 30+°F.
Conditions: Clear Partly Cloudy Cloudy Stormy

Line #: 060003-060003 Length: 374

From Manhole #: 060003 to Manhole #: 060002

Pipe Size: 15" Pipe Material: PVC VCP RCP Other: _____

Direction of televising: Upstream Downstream

Flow: None Low 1/2 pipe 3/4 pipe LS #3 shut off

Footage Observations

- 0' @ MH - 060003 BN RR yard,
- some debris in bottom of pipe
- 60' debris holding water back
- pipe looks clean again
- 125' grease cakes at joints
- 168' brick
- 189 189' joint ~~with~~ patched with brick & mortar
- ~~227~~ looks good
- 227' light roots @ joint
- 239' light roots @ joint
- 272' minimal deposit light right side south
- 272-374' debris in pipe 1/4 pipe or less
- 374' @ MH - 060002