CUES, Inc. 3600 Rio Vista Avenue Orlando, FL 32805 Phone: 407-849-0190 Fax: 407-425-1569



					PACP	Sewe	r Report	T				
Surveyed by: Paul Nelso	on	Certificate N U-1012-		Owner: CITY	OF SUPERIC	OR	Survey Customer		Drainage ar			Sheet number: 1
Work order:	Pipeline segme MH060004	ent ref: 1-MH060005		rt date/time: 14/10/16	20:36	Street: LINE BETW	EEN GARFIELD	AND BELK	NAP	City: SUPERIO	OR	
Location detai	ls:					Upstream manh MH060005			Rim t	o invert:	Grade to invert:	Rim to grade:
Downstream r MH06000				Rim to inv	ert:	Grade to invert	Rim to gr		Gewer use: SS	Direction: D	Flow contr N	ol: Height: 15
Width: Shape: Material: Ln. method:   15 C RCP			Pipe joint l	Pipe joint length:		Total length:Length surveyed405.0288.5			Year re	enewed: Media label: 776, 780		
Purpose: S	Purpose: Sewer category: Pre-cleaning Date cleaned: Weather: Location code: Additional info:   F N 1 D											
Grade	Amount of Structur Defects	Structural ral Structural Segment Grade	Structural Pipe Rating	Structural Quick Rating	Structural Pipe Rating Index	Amount of O&M Defects	O&M Segment Grade	O&M O&M Pipe Ratin	g O&M Quick Rating	O&M Pipe Rating Index		rall Pipe Overall Pipe Rating Index
1	0	0				0	0					
2	0	0				0	0					
3	0	0	0	0000	0	0	0	0	0000	0	4	4
4	0	0				0	0					
5	0	0				0	0					

CUES, Inc. 3600 Rio Vista Avenue Orlando, FL 32805 Phone: 407-849-0190 Fax: 407-425-1569



Surveyed by: Paul Nelson		Owner: CITY OF SUPERIOR				Upstream manhole No: MH060005				Pipeline segment ref: MH060004-MH060005				
Distance (Feet) (Meters)	Video Ref.	Group/ Modifier/ Descriptor Severity	Continuous Defect	S/M/L	V. Inches 1st	alue (mm) 2nd	%	Joint		ferential ation to	Image Ref.	Family	Rating	Remarks
0.0	1	AMH										CF		MH060005
0.0	20	MWL					50							
270.7	207	MWL					60							
286.4	254	MWLS					65						4	
288.5	304	MSA												WATER SAG 1000%