

Viking Pipe Services
Number: MH-050311 to MH-050310

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	6/4/99	PIPE SIZE	15" X 4'
TIME	2:34:51 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE.	LOCATION	ALONG WESTSIDE OF HILL AVE.
DWN_DESCRIPTOR	NO. 28TH ST.	LENGTH/RUN	399'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR,WISC.	FLOW_DIR	NORTH
TAPE_#	#2 SUPERIOR-MW-99	FLOW_RATE	LOW
COUNTER	01:06:52	DIR_MEASURED	WITH FLOW
SETUP_#	#11	ROAD_SURFACE	ASPHALT-CONC.
AREA	HILL AVE	MH_REPORT	NONE
PIPE_TYPE	RCP		
Comments	MINOR MINERAL		

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
7	WATER	2-4"	BOTTOM OF PIPE	START OF RUN #11, THIS IS WITH THE FLOW.
17.2	SEPERATED JOINT			MINOR
25	MINERAL AT JOINT	LIGHT		
37.3	INFILTRATION AT JOINT	LIGHT		
49.5	INFILTRATION AT JOINT	LIGHT		
55.4	WATER	2-4"	BOTTOM OF PIPE	
99.1	DEBRI		BOTTOM OF PIPE	
106	MINERAL AT JOINT	LIGHT		
118.1	INFILTRATION AT JOINT	LIGHT		
126.8	INFILTRATION AT JOINT	LIGHT		
130.3	MINERAL AT JOINT	LIGHT		
175	INFILTRATION AT JOINT	LIGHT		
182.9	INFILTRATION AT JOINT	LIGHT		
186.9	INFILTRATION AT JOINT	LIGHT		
194.9	MINERAL AT JOINT	LIGHT		
239.1	MINERAL AT JOINT	LIGHT		
243.4	MINERAL AT JOINT	LIGHT		
251.7	MINERAL AT JOINT	LIGHT		

Viking Pipe Services
Number: MH-050311 to MH-050310

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
255.7	MINERAL AT JOINT	LIGHT		
259.6	MINERAL AT JOINT	LIGHT		
271.6	MINERAL AT JOINT	LIGHT		
280.2	MINERAL AT JOINT	LIGHT		
287.9	MINERAL AT JOINT	LIGHT		
292	MINERAL AT JOINT	LIGHT		
296.3	MINERAL AT JOINT	LIGHT		
307.8	TAP TO THE LEFT		11 O/C	
324.3	INFILTRATION AT JOINT	LIGHT		
352.8	INFILTRATION AT JOINT	LIGHT		
360.8	INFILTRATION AT JOINT	LIGHT		
369.1	INFILTRATION AT JOINT	LIGHT		
377.1	INFILTRATION AT JOINT	LIGHT		
381	INFILTRATION AT JOINT	LIGHT		
399				CENTER OF MH-050310