

**Viking Pipe Services**  
**Number: MH-050314 to MH-050313**

<b>FIELD</b>	<b>VALUE</b>	<b>FIELD</b>	<b>VALUE</b>
DATE	6/4/99	PIPE SIZE	15" X 4'
TIME	12:27:30 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE.	LOCATION	ALONG WESTSIDE OF HILL AVE.
DWN_DESCRIPTOR	WESTSIDE OF HILL AVE.	LENGTH/RUN	400'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR,WISC.	FLOW_DIR	NORTH
TAPE_#	#2 SUPERIOR-MW-99	FLOW_RATE	LOW
COUNTER	00:25:24	DIR_MEASURED	WITH FLOW
SETUP_#	#07	ROAD_SURFACE	ASPHALT-CONC.
AREA	HILL AVE	MH_REPORT	SEE ATTACHED
PIPE_TYPE	RCP		
Comments	MINOR MINERAL		

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #07, THIS IS WITH THE FLOW
14.3	INFILTRATION AT JOINT	LIGHT		
18.5	MINERAL AT JOINT	LIGHT		
40	WATER	2-4"	BOTTOM OF PIPE	
94.9	MINERAL AT JOINT	LIGHT		
123.4	MINERAL AT JOINT	LIGHT		
139.3	MINERAL AT JOINT	LIGHT		
166.5	TAP TO THE LEFT		9 O/C	
204.2	MINERAL AT JOINT	LIGHT		
244.2	MINERAL AT JOINT	LIGHT		
248.5	MINERAL AT JOINT	LIGHT		
365.4	MINERAL AT JOINT	LIGHT		
400				CENTER OF MH-050313