

2-18-97 03A 307 to 03A 308

time .13830

0

upstream with 03A 308 quality poor

Flow ~~1/2~~ 3/4 pipe. foggy dark

6'

camera seems to drop down. ~~4.5 to 5.5 ft W~~

joints rough + hard to see detail.

camera goes up + down

while going over.

62'

camera stops 14109

new date 2/20/97 03A 307 - 03A 306

19'

starts Flow 1/3 pipe. quality better ^{good} to fair.

joints rough

camera goes up + down while going

37'

slight bend right over joint.

60

slight bend right.

72'

light mineral deposits. right side 3 o'clock.

127'

light mineral deposit left side 9 o'clock.

134

slight bend left.

140

light mineral deposit left side 9 o'clock.

150'

camera/screen goes black

end of recording. time 14434