

**Viking Pipe Services**  
**Number: MH-03A307A to MH-03A307**

<b>FIELD</b>	<b>VALUE</b>	<b>FIELD</b>	<b>VALUE</b>
DATE	6/7/99	PIPE SIZE	15" X 4'
TIME	1:09:50 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE	LOCATION	RUNS ALONG WESTSIDE OF HILL AVE
DWN_DESCRIPTOR	WESTSIDE OF HILL AVE	LENGTH/RUN	279'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR WISC.	FLOW_DIR	NORTH
TAPE_#	#2 SUPERIOR-MW-99	FLOW_RATE	LOW
COUNTER	01:41:10	DIR_MEASURED	WITH FLOW
SETUP_#	#02	ROAD_SURFACE	ASPHALT-CONC.
AREA	HILL AVE	MH_REPORT	NONE
PIPE_TYPE	RCP		

Comments            MINOR MINERAL

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
7				START OF RUN #02, THIS IS WITH THE FLOW
13.2	MINERAL AT JOINT	LIGHT	BOTTOM OF PIPE	
54.3	MINERAL AT JOINT	LIGHT	BOTTOM OF PIPE	
70.1	MINERAL AT JOINT	LIGHT	BOTTOM OF PIPE	
82.5	MINERAL AT JOINT	LIGHT	BOTTOM OF PIPE	
100	WATER	2-4"	BOTTOM OF PIPE	
110.7	INFILTRATION AT JOINT	LIGHT		
126.8	MINERAL AT JOINT	LIGHT	BOTTOM OF PIPE	
130.4	TAP TO THE LEFT		10 O/C	
198	TAP TO THE LEFT		10 O/C	
228.5	SAG	MANY OF THEM		MINOR
267.7	DEBRI	SMALL	BOTTOM OF PIPE	
279				CENTER OF MH-03A307