

**Viking Pipe Services**  
**Number: MH-03A307A to MH-03A308**

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	6/7/99	PIPE SIZE	15" X 4'
TIME	10:42:21 AM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE	LOCATION	RUNS ALONG
DWN_DESCRIPTOR	#2523 HILL AVE		WESTSIDE OF HILL AVE
JOB_#	17-99	LENGTH/RUN	73'
CLIENT	SUPERIOR WISC.	INSPECTOR	MW
TAPE_#	#2 SUPERIOR-MW-99	FLOW_DIR	NORTH
COUNTER	01:38:48	FLOW_RATE	LOW
SETUP_#	#01	DIR_MEASURED	AGAINST FLOW
AREA	HILL AVE	ROAD_SURFACE	ASPHALT-CONC.
PIPE_TYPE	RCP	MH_REPORT	NONE

Comments            GOOD PIPE

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
7				START OF RUN #01, THIS IS AGAINST THE FLOW
19.8	TAP TO THE RIGHT		2 O/C	
73				CENTER OF MH-03A308