

Viking Pipe Services
Number: MH-03A308A to MH-03A308

FIELD	VALUE	FIELD	VALUE
DATE	6/8/99	PIPE SIZE	15" X 4'
TIME	6:32:16 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE	LOCATION	RUNS DOWN
DWN_DESCRIPTOR	WESTSIDE OF HILL AVE		WESTSIDE OF HILL AVE
JOB_#	17-99	LENGTH/RUN	216'
CLIENT	SUPERIOR,WISC.	INSPECTOR	MW
TAPE_#	#4 SUPERIOR-MW-99	FLOW_DIR	NORTH
COUNTER	01:31:28	FLOW_RATE	LOW
SETUP_#	#14	DIR_MEASURED	WITH FLOW
AREA	HILL AVE	ROAD_SURFACE	ASPHALT-CONC.
PIPE_TYPE	RCP	MH_REPORT	NONE

Comments MINOR MINERAL & INFIL.

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #14, THIS IS WITH THE FLOW.
2.4	MINERAL AT JOINT	LIGHT		
15.2	MINERAL AT JOINT	LIGHT		
18.9	MINERAL AT JOINT	LIGHT		
52.9	TAP TO THE LEFT		10 O/C	
87.6	MINERAL AT JOINT	LIGHT		
92	MINERAL AT JOINT	LIGHT		
95.9	INFILTRATION AT JOINT	LIGHT		
104.2	INFILTRATION AT JOINT	LIGHT		
128.3	INFILTRATION AT JOINT	LIGHT		
136.4	INFILTRATION AT JOINT	LIGHT		
188.9	MINERAL AT JOINT	LIGHT		
209.4	INFILTRATION AT JOINT	LIGHT		
216				CENTER OF MH-03A308