



Inspection report

Date: 6/15/2022	Work Order:	Weather: Light Rain	Surveyed By: Steven Bucklin	Certificate Number: U-0819-70306510	Pipe Segment Ref.: MH3A308C-MH3A308A
Year laid:	Pre-cleaning: Light Cleaning	Direction: Downstream	Pipe Joint Length:	Total Length:	Length Surveyed:

City: Superior	Drainage Area:	Upstream MH: MH3A308A
Street: HILL	Media Label: 1115	Up Rim to Invert: 0.0
Location Code: Local rural streets with light traffic	Flow Control: Lift Station	Downstream MH: MH3A308C
Location Details:	Sheet Number:	Down Rim to Invert: 0.0
Pipe shape: Circular	Sewer Use: Sanitary Sewage Pipe	Total gallons used: 0.0
Pipe size: 15	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method: None	Owner: City of Superior	

Additional Info:

1:1586	Distance	Code	Observation	Counter	Photo	Grade		
MH3A308A								
	0.0	AMH	Manhole / MH3A308A	00:00:01	MH3A308 C-MH3A30 8A_e50b5			
	0.0	MWL	Water Level, 5% of the vertical dimension	00:01:11	MH3A308 C-MH3A30 8A_4d881			
	2.9	S01	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 9 o'clock to 3 o'clock, within 8 inch, Start	00:01:59	MH3A308 C-MH3A30 8A_9ad12		
	3.7	S02	SAP	Surface Damage Aggregate Projecting from 9 o'clock to 3 o'clock, within 8 inch, Start	00:03:13	MH3A308 C-MH3A30 8A_a5f389		
	23.2	SRV	Surface Damage Reinforcement Visible from 2 o'clock to 3 o'clock, within 8 inch	00:05:17	MH3A308 C-MH3A30 8A_ca22e	S4		
	48.8	B	Broken from 10 o'clock to 12 o'clock	00:07:32	MH3A308 C-MH3A30 8A_cb43b	S4		
	48.8	TBI	Tap Break-In Intruding at 11 o'clock, dia/height: 4inch, intruding: 1inch / ACTIVITY.	00:07:53	MH3A308 C-MH3A30 8A_17eb1	M2		
	79.8	DAR	Deposits Attached Ragging, 5% of cross sectional area at 4 o'clock, within 8 inch	00:11:11	MH3A308 C-MH3A30 8A_8b19b	M2		
	136.2	SRV	Surface Damage Reinforcement Visible from 2 o'clock to 3 o'clock, within 8 inch	00:14:16	MH3A308 C-MH3A30 8A_ae945	S4		
	140.3	DAR	Deposits Attached Ragging, 5% of cross sectional area at 4 o'clock, within 8 inch	00:14:42	MH3A308 C-MH3A30 8A_18c1a	M2		
	208.6	F01	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 9 o'clock to 3 o'clock, within 8 inch, Finish	00:18:18	MH3A308 C-MH3A30 8A_ebf53e	M2	
	208.6	F02	SAP	Surface Damage Aggregate Projecting from 9 o'clock to 3 o'clock, within 8 inch, Finish	00:18:26	MH3A308 C-MH3A30 8A_209c4	S3	
	210.0	AMH	Manhole / MH3A308C	00:21:13	MH3A308 C-MH3A30 8A_e8b5a			
MH3A308C								
QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
433G	2G00	433G	135.0	88.0	223.0	3.1	2.0	2.5