



**Stack Bros.**  
3119 Hill Ave. Superior WI

Tel: 7153982964

Fax:

E-mail:

## Inspection Report

MH060112-MH060114

Date <b>5/17/2019</b>	P/O. No. <b>104790</b>	Weather <b>Dry</b>	Surveyor's Name <b>Josh Gordon</b>	Pipe Segment Reference <del>MH060114 - MH06112A</del>	Section No. <b>5</b>
Certificate No. <b>U-215-06023623</b>	Survey Customer	System Owner	Preset :	Pre-Cleaning <b>Not Known</b>	Sewer Category

Street <b>Culdesack on St. Albans</b>	Use of Sewer <b>Sanitary</b>	Upstream MH <b>MH060114</b>
City <b>City of Superior</b>	Drainage Area <b>District 6</b>	Downstream MH <del>MH06112A</del> MH060112
Loc. details	Flow Control	Dir. of Survey <b>Downstream</b>
Location Code <b>Light Highway</b>	Length surveyed <b>413.29 ft</b>	Section Length <b>413.29 ft</b>

Purpose of Survey <b>Routine Assessment</b>	Joint Length	<b>10 inch</b>
Year Laid	Dia./Height	<b>Vitrified Clay Pipe</b>
Year Rehabilitated <del>1000</del>	Material	
Tape / Media No. <b>982</b>	Lining Method	

Add. Information : **Inspection indicates that structure MH06112A between MH060112 and MH060114 doesn't exist.**


1:792	Position	Code	Observation	Photo	Grade
	0.00	AMH	Manhole, MH060114 / MH060114		
	0.00	MWL	Water Level, 5 % of cross sectional area		
			REFER TO TELEVISION INSPECTION FROM MH06112A-MH060114 20190425 DOWNSTREAM FOR INSPECTION BTW 0FT-266.83FT		
	266.83	CM	Crack Multiple, from 11 o'clock, to 1 o'clock, within 8 inch		
	268.01	MWLS	Water Level, Sag in pipe, 40 % of cross sectional area		
	277.20	CM	Crack Multiple, from 12 o'clock, to 1 o'clock, within 8 inch		
	281.36	CL	Crack Longitudinal, at 12 o'clock, within 8 inch		
	282.35	B	Broken, from 11 o'clock, to 1 o'clock, within 8 inch		
	292.72	FM	Fracture Multiple, from 7 o'clock, to 5 o'clock, within 8 inch		
	295.83	FM	Fracture Multiple, from 7 o'clock, to 5 o'clock, within 8 inch		
	297.64	TFA	Tap Factory Made Active, at 3 o'clock, 10 inch dim, within 8 inch		CONNECTION FROM IN060559
	299.21	FM	Fracture Multiple, from 7 o'clock, to 5 o'clock, within 8 inch		
	305.54	FM	Fracture Multiple, from 7 o'clock, to 5 o'clock, within 8 inch		
	305.54	LD	Alignment Down, 10 % changed		
	312.20	CS	Crack Spiral, from 5 o'clock, to 6 o'clock, within 8 inch		



**Stack Bros.**  
 3119 Hill Ave. Superior WI  
 City :  
 Tel: 7153982964  
 Fax:  
 Email:

## Inspection Report

Date	P/O. No.	Weather <b>Dry</b>	Surveyor's Name <b>Josh Gordon</b>	Pipe Segment Reference	Section No.
Certificate No. <b>U-215-06023623</b>	Survey Customer	System Owner	Preset :	Cleaned : <b>Not Known</b>	Sewer Category

1:792	Position	Code	Observation	Photo	Rate		
	<u>312.70</u>	TFA	Tap Factory Made Active, at 9 o'clock, 8 inch dim CONNECTION FROM IN060558				
	<u>315.72</u>	TFA	Tap Factory Made Active, at 3 o'clock, 8 inch dim CONNECTION from MH060113				
	<u>322.28</u>	TFC	Tap Factory Made Capped, at 9 o'clock, 8 inch dim				
	<u>325.89</u>	CM	Crack Multiple, from 11 o'clock, to 3 o'clock, within 8 inch				
	<u>392.59</u>	D	Deformed, 5 % changed				
	<u>413.22</u>	TBA	Tap Break-In Active, at 10 o'clock, 4 inch dim				
	<u>413.29</u>	MSA	Survey Abandoned, intruding tap / intruding tap				
QSR	QMR	SPR	MPR	OPR	SPRI	MPRI	OPRI