

1:294

Position

Stack Bros. 3119 Hill Ave. Superior WI

Tel: 7153982964 Fax: E-mail:

Photo

Grade

Inspection Report

		-	MH060112-MH060114			
Date P/O. No.		Weather	Surveyor's Name	Pipe Segment Reference	Section No.	
5/17/2019 104790		Dry	Josh Gordon	MH06112A-1 - MH060112-	6	
Certificate No. Survey Customer U-215-06023623		System Owner	Preset :	Pre-Cleaning Not Known	Sewer Category	

Street City	On St. Albans SE of Newton & ত্তীtyAঞ্চিক্তাফুচerior		itary rict 6	Upstream MH Dowstream MH	-MH06112A-1 MH060114 -MH060112-1 MH060112	
Loc. details		Flow Control		Dir. of Survey	Upstream	
Location Code	Light Highway	Length surveyed 113	.39 ft	Section Length	113.39 ft	
Purpose of Survey	V Routine Assessment		Joint Length			

Year Laid

Code

Dia./Height 10 inch

1000 Material Year Rehabilitated Vitrified Clay Pipe Tape / Media No. 982 Lining Method

 $\textbf{Add. Information:} \quad \textbf{Inspection indicates that structure MH06112A between MH060112 and MH060114 doesn't exist.}$

Observation

	MH060112-1	0.00	АМН	Manho	ole, MH060112 / M	1 H060112			
		0.00	MWL	Water	Level, 10 % of cro	oss sectional area			
		0.49	HVV	Hole \	oid Visible, from 3	3 o'clock, to 5 o'clo	ck, within 8 inch		
		0.49	JOL	Joint (Offset Large, 0 ° di	splacement			
		27.26	MWL	Water	Level, 5 % of cros	s sectional area			
 		<u>32.15</u>	CL	Crack	Longitudinal, at 1	o'clock			
		34.35 CM Crack Multiple, from 12 o'clock, to 2 o'clock							
		<u>44.19</u>	TFA	Tap F	actory Made Active	e, at 10 o'clock, 8 i	nch dim		
	1	TBA MSA			3 o'clock, 4 inch dir uding tap; reversal				
	2	<u>13.39</u>	IVIOA	intrudi	y Abandoned, Intro ng tap; reversal co	omplete	complete /		
						<u> </u>			
	QSR	QMR	SPR	!	MPR	OPR	SPRI	MPRI	OPRI