

# MEDIA # 378

**PACP© Inspection Form**

Surveyors Name Mickey Webster		Certificate Number T-605-2280		System Owner City of Superior		Survey Customer City of Superior		Drainage Area District 06		Sheet No. 1 of 1	
P/O No.	Pipe Segment Reference UNKown-IN060591		Date 2007/10/09	Time 08:36	Location (Street Name and Number) 21st & New York		Locality (City) Superior				
Further Location Details					Upstream Manhole Number IN060591		Rim to Invert	Grade to Invert	Rim to Grade		
Downstream Manhole Number Unknown		Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction Downstream	Flow Control		Height 15 in.		
Width	Shape Circular	Material Clay Tile	Ln. Method	Joint Length 82.7 ft.	Total Length 82.7 ft.	Length Surveyed 82.7 ft.	Year Laid	Year Rehab.	Tape/Media No. 1		
Purpose		Sewer Category	Pre-Cleaning Jetting	Cleaned	Weather Light Rain	Location Code		Additional Information			

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				IN060591
0.00		Miscellaneous	Water Level					0	<input type="checkbox"/>				
5.00		Crack	Longitudinal						<input type="checkbox"/>	10			
6.60		Crack	Longitudinal						<input type="checkbox"/>	3			
10.70		Crack	Multiple						<input type="checkbox"/>	10	11		
13.50		Joint	Separated	Large					<input type="checkbox"/>				
17.00		Crack	Longitudinal						<input type="checkbox"/>	11			
20.60		Crack	Longitudinal						<input type="checkbox"/>	10			
22.70		Crack	Longitudinal						<input type="checkbox"/>	4			
41.60		Joint	Separated	Large					<input type="checkbox"/>				
70.30		Miscellaneous	Camera Underwater						<input type="checkbox"/>				Wire mess patch
82.70		Access Point	Manhole						<input type="checkbox"/>				Unknown