

Media #382

**PACP® Inspection Form**

Surveyors Name Mickey Webster	Certificate Number T-605-2280	System Owner City of Superior	Survey Customer City of Superior	Drainage Area District 01	Sheet No. 1 of 1				
P/O No.	Pipe Segment Reference ST010151-ST010352	Date 2007/10/30	Time 08:02	Location (Street Name and Number) 1st / Hughitt	Locality (City) Superior				
Further Location Details			Upstream Manhole Number ST010352	Rim to Invert	Grade to Invert	Rim to Grade			
Downstream Manhole Number ST010151	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer Stormwater	Direction Downstream	Flow Control	Height 36 in.		
Width	Shape Circular	Material Brick	Ln. Method	Joint Length 109.8 ft.	Total Length 109.8 ft.	Length Surveyed 109.8 ft.	Year Laid	Year Rehab.	Tape/Media No. 382
Purpose	Sewer Category	Pre-Cleaning Jetting	Cleaned	Weather Dry	Location Code	Additional Information			

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				ST010352
0.00		Miscellaneous	Water Level					0	<input type="checkbox"/>				
38.20		Point Repair	Patch						<input type="checkbox"/>	11	1		
58.00		Tap	Break-in	Intruding		6	2		<input type="checkbox"/>	3			
88.70		Point Repair	Patch						<input type="checkbox"/>	11	12		
100.00		Miscellaneous	General Observation						<input type="checkbox"/>				Debris in line
109.80		Miscellaneous	General Observation						<input type="checkbox"/>				Debris in Line
109.80		Miscellaneous	Survey Abandoned						<input type="checkbox"/>				Clay in Line
109.80		Access Point	Manhole						<input type="checkbox"/>				Clay in Line