

PACFP © Inspection Form

Surveyors Name Certificate Number System Owner Survey Customer Drainage Area Sheet No.
 Mickey Webster T-605-2280 City of Superior City of Superior District 05 1 of 1

P/O No. Pipe Segment Reference Date Time Location (Street Name and Number) Locality (City)
 MH050048-MH05North 2008/1/03 10:57 Baxtor & Lamborn / 58th / 57th Superior

Further Location Details Upstream Manhole Number Rim to Invert Grade to Invert Rim to Grade
 MH050048 MH050048

Downstream Manhole Number Rim to Invert Grade to Invert Rim to Grade Use of Sewer Direction Flow Control Height
 MH05North Sanitary Upstream 8 in.

Width Shape Material Ln. Method Joint Length Total Length Length Surveyed Year Laid Year Rehab. Tape/Media No.
 Circular Polyvinyl Chloride 166.1 ft. 166.1 ft. 166.1 ft. 441

Purpose Sewer Category Pre-Cleaning Cleaned Weather Location Code Additional Information
 Routine Assessment Not Known Dry Alley

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	AV From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH050048
0.00		Miscellaneous	Water Level					5	<input type="checkbox"/>				
18.40		Miscellaneous	General Observation						<input type="checkbox"/>				Bug in line
155.10		Tap	Factory Made		6				<input type="checkbox"/>	10			
166.10		Miscellaneous	Survey Abandoned						<input type="checkbox"/>				Debris in line
166.10		Access Point	Manhole						<input type="checkbox"/>				Debris in line