

PACP® Inspection Form

| | | | | | | | | | |
|-------------------------------------|---|----------------------------------|-------------------------------------|--|-----------------------------|----------------------------|------------------|-------------|-----------------------|
| Surveyors Name Mickey Webster | Certificate Number T-605-2280 | System Owner City of Superior | Survey Customer City of Superior | Drainage Area District 02 | Sheet No. 1 of 1 | | | | |
| P/O No. | Pipe Segment Reference MH12st-MH13th | Date 2008/06/09 | Time 13:14 | Location (Street Name and Number) 12th / Catlin & Birch | Locality (City) Superior | | | | |
| Further Location Details Alley | | | Upstream Manhole Number MH12th | Rim to Invert | Grade to Invert | Rim to Grade | | | |
| Downstream Manhole Number MH13th | Rim to Invert | Grade to Invert | Rim to Grade | Use of Sewer Other | Direction Upstream | Flow Control | Height 18 in. | | |
| Width | Shape Circular | Material Clay Tile | Ln. Method | Joint Length 9.3 ft. | Total Length 9.3 ft. | Length Surveyed 9.3 ft. | Year Laid | Year Rehab. | Tape/Media No. 406 |
| Purpose | Sewer Category | Pre-Cleaning Not Known | Cleaned | Weather Dry | Location Code | Additional Information | | | |

| Distance (Feet) | Video Ref. | Group | Description | Modifier | Cont. Defect | Inches 1st | Inches 2nd | % | Joint | At/From | To | Image Ref. | Remarks |
|-----------------|------------|---------------|------------------|----------|--------------|------------|------------|---|--------------------------|---------|----|------------|----------------|
| 0.00 | | Access Point | Manhole | | | | | | <input type="checkbox"/> | | | | MH12th |
| 0.00 | | Miscellaneous | Water Level | | | | | 5 | <input type="checkbox"/> | | | | |
| 9.30 | | Miscellaneous | Survey Abandoned | | | | | | <input type="checkbox"/> | | | | Debris in Line |
| 9.30 | | Access Point | Manhole | | | | | | <input type="checkbox"/> | | | | Debris in Line |