

MANHOLE INSPECTION REPORT

MH020401

Priority: 2

InspectionID:	145025	Manhole Number:	MH020401
Surveyed By:	Andrew Rausch	Rim to Invert (ft):	16.02
Street	d Avenue btw Belknap & N16th Street	Rim to Grade (ft):	0
Date:	20211103	Purpose:	Routine assessment
Time:	14:18	Potential for Runoff:	Sheeting
Manhole Use:	Combined	Inspection Status:	Surface Inspection
Elevation:		Cover Frame Fit:	Good
Northing:		Easting:	

Cover Size(in): 25.25 Cover Material: Cast Iron

- | | |
|---|---|
| <input type="checkbox"/> Cover Type Solid | <input checked="" type="checkbox"/> Cover Condition Sound |
| <input checked="" type="checkbox"/> Cover Type Vented | <input type="checkbox"/> Cover Condition Cracked |
| <input type="checkbox"/> Cover Type Gasketed | <input type="checkbox"/> Cover Condition Broken |
| <input type="checkbox"/> Cover Type Bolted | <input type="checkbox"/> Cover Condition Corroded |
| <input type="checkbox"/> Cover Type Inner Cover | <input type="checkbox"/> Cover Condition BoltsMissing |
| <input type="checkbox"/> Cover Type Locking | <input type="checkbox"/> Cover Condition Missing |

- | | |
|---|-------------------------------|
| <input checked="" type="checkbox"/> Frame Condition Sound | Frame Offset Distance (in): 2 |
| <input type="checkbox"/> Frame Condition Cracked | Frame Seal Inflow: None |
| <input type="checkbox"/> Frame Condition Broken | Frame Depth (in): 8.5 |
| <input type="checkbox"/> Frame Condition Missing | Frame Material: Cast Iron |
| <input type="checkbox"/> Frame Condition Corroded | Adjustment Ring Type: None |
| <input type="checkbox"/> Frame Condition Coated | Adjustment Ring Height (in): |

- | | |
|--|---|
| <input type="checkbox"/> Ring Condition Sound | <input type="checkbox"/> Ring Condition PoorInstall |
| <input type="checkbox"/> Ring Condition Cracked | <input type="checkbox"/> Ring Condition Leaking |
| <input type="checkbox"/> Ring Condition Broken | <input type="checkbox"/> Ring Condition Corroded |
| <input checked="" type="checkbox"/> Seal Condition Sound | <input type="checkbox"/> Seal Condition Offset |
| <input type="checkbox"/> Seal Condition Cracked | <input type="checkbox"/> Seal Condition Loose |

Chimney Depth(ft):	3.39	Chimney Material:	Brick
Cone Depth(ft):	7.69	Cone Material:	Brick
Wall Depth(ft):	12.35	Bench Material:	
Channel Type:	Pipe	Step Material:	Metal
Cone Type:	Conical centered	Channel Exposure:	Fully Opened

MANHOLE INSPECTION REPORT

MH020401

Priority: 2

Manhole Pipe Connections

<i>Clock</i>	<i>Invert</i>	<i>Direction</i>	<i>Material</i>	<i>Shape</i>	<i>D1</i>	<i>D2</i>	<i>Structure ID</i>
6	16.02	Out	Brick	Egg Shaped	66		MH020400-MH020401
11	15.91	In	Brick	Egg Shaped	66		MH020401-MH020402
11	7.09	In	Reinforced Concrete Pipe	Circular	15		

Manhole Defects

<i>Distance (ft)</i>	<i>MH Component ID</i>	<i>MACP Code</i>	<i>Joint</i>	<i>C1</i>	<i>C2</i>	<i>Continuous</i>
0.68	CMI	MMS	<input type="checkbox"/>	12	12	S01
1.96	CMI	MMS	<input type="checkbox"/>	12	12	F01