

PACP® Inspection Form

Surveyors Name Dave Sigfrids **Certificate Number** T-605-2213 **System Owner** City of Superior **Survey Customer** City of Superior **Drainage Area** District 05 **Sheet No.** 1 of 1
P/O No. **Pipe Segment Reference** MH050048-MHNNorth **Date** 2009/03/02 **Time** 10:04 **Location (Street Name and Number)** 58th / Lamborn & Baxtor **Locality (City)** Superior
Further Location Details **Upstream Manhole Number** MH050048 **Rim to Invert** **Grade to Invert** **Rim to Grade** **Flow Control** **Height** 8 in.
Downstream Manhole Number MHNNorth **Rim to Invert** **Grade to Invert** **Rim to Grade** **Direction** Upstream **Year Laid** **Year Rehab.** 450
Width **Shape** Circular **Material** Polyvinyl Chloride **Ln. Method** **Joint Length** 247.5 ft. **Total Length** 247.5 ft. **Length Surveyed** 247.5 ft. **Year Laid** **Year Rehab.** 450
Purpose **Sewer Category** **Pre-Cleaning** **Cleaned** **Weather** **Location Code** **Additional Information**
Routine Assessment **Sewer Category** Not Known **Weather** Dry **Location Code** Alley

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH050048
0.00		Miscellaneous	Water Level				0		<input type="checkbox"/>				
155.10		Tap	Factory Made		4	4			<input type="checkbox"/>	10			
167.50		Tap	Factory Made	Capped	4	4			<input type="checkbox"/>	2			
167.60		Infiltration	Weeper						<input type="checkbox"/>	2	5		
247.50		Access Point	Manhole						<input type="checkbox"/>				MHNNorth