

PACP© Inspection Form

Surveyors Name Mickey Webster	Certificate Number T-605-2280	System Owner City of Superior	Survey Customer City of Superior	Drainage Area District 02	Sheet No. 1 of 1				
P/O No. 	Pipe Segment Reference MH12st-MH??	Date 2008/06/09	Time 13:29	Location (Street Name and Number) 12th / Catlin & Birch	Locality (City) Superior				
Further Location Details Alley to East			Upstream Manhole Number MH12th	Rim to Invert 	Grade to Invert 	Rim to Grade 			
Downstream Manhole Number MH??	Rim to Invert 	Grade to Invert 	Rim to Grade 	Use of Sewer Other	Direction Upstream	Flow Control 	Height 18 in.		
Width 	Shape Circular	Material Clay Tile	Ln. Method 	Joint Length 27.8 ft.	Total Length 27.8 ft.	Length Surveyed 27.8 ft.	Year Laid 	Year Rehab. 	Tape/Media No. 406
Purpose 	Sewer Category 	Pre-Cleaning Not Known	Cleaned 	Weather Dry	Location Code 	Additional Information 			

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH12th
0.00		Miscellaneous	Water Level					5	<input type="checkbox"/>				
16.10		Crack	Multiple						<input type="checkbox"/>	9	3		
27.80		Access Point	Manhole						<input type="checkbox"/>				Debris in Line
27.80		Miscellaneous	Survey Abandoned						<input type="checkbox"/>				Debris in Line