

**PACP® Inspection Form**

**Surveyors Name** David Sigfrids **Certificate Number** U-605-2213 **System Owner** City of Superior **Survey Customer** City of Superior **Drainage Area** **Sheet No.** 1 of 1  
**P/O No.** MH010171-MH010010 **Date** 2023/06/28 **Time** 09:26 **Location (Street Name and Number)** 3rd Street & Banks **Locality (City)** Superior **Rim to Invert** **Grade to Invert** **Rim to Grade**  
**Further Location Details** **Upstream Manhole Number** MH010010 **Use of Sewer** Sanitary **Direction** Downstream **Flow Control** **Height** 10 in.  
**Downstream Manhole Number** MH 010171 **Rim to Invert** **Grade to Invert** **Rim to Grade** **Joint Length** 47.6 ft. **Total Length** 47.6 ft. **Year Laid** **Year Rehab.** 1133  
**Width** **Shape** Circular **Material** Reinforced Concrete F **Ln. Method** **Joint Length** 47.6 ft. **Length Surveyed** 47.6 ft. **Year Laid** **Year Rehab.** 1133  
**Purpose** **Sewer Category** **Pre-Cleaning** **Cleaned** **Weather** **Location Code** **Additional Information**

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/ From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH010010
0.00		Miscellaneous	Water Level				5		<input type="checkbox"/>				
22.00		Deposits	Attached	Encrustation	S01		5	90	<input type="checkbox"/>	3	9		
47.60		Collapse	Pipe Sewer						<input type="checkbox"/>				
47.60		Deposits	Attached	Encrustation	F01		5		<input type="checkbox"/>	3	9		
47.60		Miscellaneous	Survey Abandoned						<input type="checkbox"/>				Pipe Caved In
47.60		Access Point	Manhole						<input type="checkbox"/>				Pipe Caved In