

PACP© Inspection Form

Surveyors Name Dave Sigfrids		Certificate Number T-605-2213		System Owner City of Superior		Survey Customer City of Superior		Drainage Area District 02		Sheet No. 1 of 1	
P/O No.	Pipe Segment Reference MH02437G-MH060001		Date 2011/03/07	Time 10:40	Location (Street Name and Number) West of Oaks and Belknap			Locality (City) Superior			
Further Location Details					Upstream Manhole Number MH02437G		Rim to Invert	Grade to Invert	Rim to Grade		
Downstream Manhole Number MH060001		Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer Combined		Direction Upstream	Flow Control	Height 15 in.		
Width	Shape Circular	Material Reinforced Concrete F	Ln. Method	Joint Length 25.7 ft.	Total Length 25.7 ft.	Length Surveyed 25.7 ft.	Year Laid	Year Rehab.	Tape/Media No. 610		
Purpose Infiltration/Inflow Investigat		Sewer Category	Pre-Cleaning Not Known	Cleaned	Weather	Location Code	Additional Information				

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/ From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH02437G
0.00		Miscellaneous	Water Level					10	<input type="checkbox"/>				
25.70		Miscellaneous	Survey Abandoned						<input type="checkbox"/>				High water
25.70		Access Point	Manhole						<input type="checkbox"/>				High water