CUES, Inc.

3600 Rio Vista Avenue Orlando, FL 32805 Phone: 407-849-0190

Fax: 407-425-1569



PACP Sewer Report																
Surveyed by: Certificate No: Owner: Paul Nelson U-1012-16021 CITY OF SUR						Survey Customer ERIOR				ea: CT 6		Sheet number:				
Work order:         Pipeline segment ref:         Start date/time:           MH060001-MH060002         2014/10/16         22:58							Street: City:  EASEMENT BY RAILROADS OFF OF ELMIRA ST AND BELKNAP  City:  SUPERIOR									
Location details:							nole No:		Rim to invert: Grade to invert:			Rim to grade:				
Downstream manhole No: Rim to invert: MH060001					ert:	Grade to invert: Rim to grade:			SS Direction:		Flow contro	ol: Height:				
Width: 15	Shape:	Material:	Pipe joint I	Pipe joint length:		Total length: Length survers 385.0 42.1		rveyed: Year laid:		Year renewed:						
Purpose: S		Pre-cleaning Dat	Weather:	Location code D	: Additional	l info:										
Grade	Amount of Structur Defects	Structural al Structural Segment Grade	Structural Pipe Rating	Structural Quick Rating	Structural Pipe Rating Index	Amount of O&M Defects	O&M Segment Grade	O&M O&M Pipe Ratin	g O&M Quick Rating	O&M Pipe Rating Index		all Pipe Overall Pipe Rating Index				
1	0	0				5	5									
2	0	0				0	0									
3	0	0	0	0000	0	3	9	18	4133	2	18	2				
4	0	0				1	4									
5	0	0				0	0									

CUES, Inc. 3600 Rio Vista Avenue Orlando, FL 32805 Phone: 407-849-0190 Fax: 407-425-1569



Surveyed by: Owner: Start date/time: Upstream manhole No: Pipeline segment ref: Sheet number:

Paul Nelson CITY OF SUPERIOR 2014/10/16 MH060002 MH060001-MH060002 2

Distance (Feet) (Meters)	Video Ref.	Group/ Modifier/ Descriptor Severity	Continuous Defect	S/M/L	Value Inches (mm)		%	Joint	Circumferential Location		Image Ref.	Family	Rating	Remarks
					1st	2nd			At/From	to				
0.0	3	АМН										CF		MH060001
0.0	19	MWL					50							
0.2	46	RFJ	S01					J	9	3		O&M	1	
26.0	399	RFJ	F01					J	9	3		O&M	1	
26.0	412	RMJ	S02				30	J	9	3		O&M	3	
41.8	836	RMJ	F02				30	J	9	3		O&M	3	
41.8	855	RBJ					90	J	7	4		O&M	4	
42.1	1060	MSA												ROOT BALL TO STRONG