



## Inspection report

Date: <b>6/3/2022</b>	Work Order:	Weather: <b>Dry</b>	Surveyed By: <b>Steven Bucklin</b>	Certificate Number: <b>U-0819-70306510</b>	Pipe Segment Ref.: <b>MH060002-MH060003</b>
Year laid:	Pre-cleaning: <b>Heavy Cleaning</b>	Direction: <b>Upstream</b>	Pipe Joint Length:	Total Length:	Length Surveyed:

City: <b>City of Superior</b>	Drainage Area:	Upstream MH: <b>MH060003</b>
Street: <b>BELKNAP</b>	Media Label: <b>1111</b>	Up Rim to Invert: <b>0.0</b>
Location Code: <b>Easement/Right of way</b>	Flow Control: <b>Lift Station</b>	Downstream MH: <b>MH060002</b>
Location Details: <b>SOUTH OF BELKNAP, BY THE RAILROAD</b>	Sheet Number: <b>16</b>	Down Rim to Invert: <b>0.0</b>
Pipe shape: <b>Circular</b>	Sewer Use: <b>Combined Pipe</b>	Total gallons used: <b>0.0</b>
Pipe size: <b>15</b>	Sewer Category: <b>SEC</b>	Joints passed: <b>0</b>
Pipe material: <b>Reinforced Concrete Pipe</b>	Purpose: <b>Routine Assessment</b>	Joints failed: <b>0</b>
Lining Method: <b>None</b>	Owner: <b>City of Superior</b>	

Additional Info:

1:2807	Distance	Code	Observation	Counter	Photo	Grade		
<b>MH060002</b>								
	0.0	AMH	Manhole / MH060002	00:00:01	MH060002 -MH06000 3_d75015			
	0.0	MWL	Water Level, 5% of the vertical dimension	00:01:18	MH060002 -MH06000 3_77be8ac			
	183.2	RPP	Point Repair Patch from 9 o'clock to 3 o'clock, within 8 inch / REPAIRED WITH BRICK	00:11:44	MH060002 -MH06000 3_23bff20			
	301.8	S01 DSF	Deposits Settled Fine, 5% of cross sectional area from 5 o'clock to 7 o'clock, within 8 inch, Start	00:19:00	MH060002 -MH06000 3_6dba9a			
	340.4	S02 DSGV	Deposits Settled Gravel, 40% of cross sectional area from 4 o'clock to 8 o'clock, within 8 inch, Start	00:22:11	MH060002 -MH06000 3_dd1d25			
	371.7	F01 DSF	Deposits Settled Fine, 5% of cross sectional area from 5 o'clock to 7 o'clock, within 8 inch, Finish	00:25:48	MH060002 -MH06000 3_642153	M2		
	371.7	F02 DSGV	Deposits Settled Gravel, 40% of cross sectional area from 4 o'clock to 8 o'clock, within 8 inch, Finish	00:27:45	MH060002 -MH06000 3_99241f6	M5		
	371.8	AMH	Manhole / MH060003	00:28:15	MH060002 -MH06000 3_55482f2			
QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
0000	562A	562A	0.0	58.0	58.0	0.0	2.9	2.9