CUES, Inc.

3600 Rio Vista Avenue Orlando, FL 32805

Phone: 407-849-0190 Fax: 407-425-1569



					PACP	Sewe	r Report									
· ·				Owner: CITY	OF SUPERIO		Survey Customer		Drainage ar		Sheet number:					
Work order: Pipeline segment ref: Start date/time: MH060006-MH060007 2014/10/16 17:40							Street: City: ALLEY BTW LOGAN & GARFIELD AND BTW BELKNAP & 16TH City: SUPERIOR									
Location detail	s:					Upstream manh	ole No:		Rim t	o invert:	Grade to invert:	Rim to grade:				
Downstream manhole No: Rin MH060006					ert:	Grade to invert: Rim to g		rade: Sewer use:		Direction:	Flow contr	ol: Height:				
Width: Shape: Material: Ln. method: 15 C RCP			Pipe joint I	Pipe joint length:		Total length: Length su 368.0 393.6				Year renewed:						
Purpose: S	urpose: Sewer category: Pre-cleaning Date cleaned: Weather: Location code: Additional info: N															
Grade	Amount of Structur Defects	Structural al Structural Segment Grade	Structural Pipe Rating	Structural Quick Rating	Structural Pipe Rating Index	Amount of O&M Defects	O&M Segment Grade	O&M O&M Pipe Ratin	g O&M Quick Rating	O&M Pipe Rating Index		all Pipe Overall Pipe Rating Index				
1	0	0				1	1									
2	0	0				0	0									
3	0	0	0	0000	0	0	0	1	1100	1	1	1				
4	0	0				0	0									
5	0	0				0	0									

CUES, Inc. 3600 Rio Vista Avenue Orlando, FL 32805 Phone: 407-849-0190 Fax: 407-425-1569



Surveyed by: Owner: Start date/time: Upstream manhole No: Pipeline segment ref: Sheet number:

Paul Nelson CITY OF SUPERIOR 2014/10/16 MH060007 MH060006-MH060007 2

Distance (Feet) Video Ref. (Meters)		Group/ Modifier/ Descriptor Severity	Continuous Defect	S/M/L	Value S/M/L Inches (mm)		%	Joint	Circumferential Location		Image Ref.	Family	Rating	Remarks
					1st	2nd			At/From	to				
0.0	5	АМН										CF		MH060007
0.0	18	MWL					35							
230.5	256	RFJ						J	12			O&M	1	
393.6	457	АМН										CF		MH060006