



Tel:
Fax:
E-mail:

Inspection Report

MH060006-MH060007

| | | | | | |
|--|-----------------|-----------------------|---------------------------------------|---|-------------------------|
| Date 9/30/2020 | P/O. No. | Weather Dry | Surveyor's Name Josh Gordon | Pipe Segment Reference MH060007 - MH060006 | Section No. 2 |
| Certificate No. U-215-06023623 | Survey Customer | System Owner | Preset : | Pre-Cleaning No Pre-Cleaning | Sewer Category |

| | | |
|---|------------------------------------|-------------------------------------|
| Street BTW Belknap & N 16th; BTW Logan & Garfield | Use of Sewer Sanitary | Upstream MH MH060007 |
| City Superior | Drainage Area District 6 | Dowstream MH MH060006 |
| Loc. details | Flow Control | Dir. of Survey Downstream |
| Location Code Yard | Length surveyed 18.24 ft | Section Length 18.24 ft |

| | |
|---|---|
| Purpose of Survey Maintenance Related | Joint Length |
| Year Laid | Dia./Height 15 inch |
| Year Rehabilitated 1000 | Material Reinforced Concrete Pipe |
| Tape / Media No. 1041 | Lining Method |

Add. Information :

| 1:56 | Position | Code | Observation | Photo | Grade |
|--|----------|------|---|-------|-------|
| | | AMH | Manhole, MH060007 / MH060007 | | |
| | | MWL | Water Level, 70 % of cross sectional area | | |
| <p>MH060006-MH060007 202009303 DOWNSTREAM Location: Alley between Belknap Street & North 16th Street and between Logan Avenue & Garfield Avenue. Pipe: 15" RCP Purpose: Sink hole is located approximately 16ft east of MH060007. Total Length: 392ft Video Location: \\ESDFILESERVER\Sewer Main CCTV\District 06\MH060006-MH060007 Priority: 1 Results: No tracer dye was seen entering the pipe. Inspection went 18ft going downstream.</p> | | | | | |
| | | MSA | Survey Abandoned, no dye visible / no dye visible | | |

| | | | | | | | |
|-----|-----|-----|-----|-----|------|------|------|
| QSR | QMR | SPR | MPR | OPR | SPRI | MPRI | OPRI |
|-----|-----|-----|-----|-----|------|------|------|