

**PACP© Inspection Form**

Surveyors Name: David Sigfrids  
 Certificate Number: U-605-2213  
 System Owner: City of Superior  
 Survey Customer: City of Superior  
 Drainage Area: \_\_\_\_\_  
 Sheet No.: 1 of 1

P/O No.: \_\_\_\_\_  
 Pipe Segment Reference: MH010021-LH010022  
 Date: 2023/06/28  
 Time: 08:23  
 Location (Street Name and Number): Cumming Ave. & 2nd Street  
 Locality (City): Superior

Further Location Details: \_\_\_\_\_  
 Upstream Manhole Number: LH010022  
 Rim to Invert: \_\_\_\_\_  
 Grade to Invert: \_\_\_\_\_  
 Rim to Grade: \_\_\_\_\_

Downstream Manhole Number: MH010021  
 Rim to Invert: \_\_\_\_\_  
 Grade to Invert: \_\_\_\_\_  
 Rim to Grade: \_\_\_\_\_  
 Height: 10 in.

Width: \_\_\_\_\_  
 Shape: Circular  
 Material: Clay Tile  
 Ln. Method: \_\_\_\_\_  
 Joint Length: 3 ft.  
 Total Length: 3 ft.  
 Length Surveyed: \_\_\_\_\_  
 Year Laid: \_\_\_\_\_  
 Year Rehab.: 1133

Purpose: \_\_\_\_\_  
 Sewer Category: \_\_\_\_\_  
 Pre-Cleaning: \_\_\_\_\_  
 Jetting: \_\_\_\_\_  
 Cleaned: \_\_\_\_\_  
 Weather: \_\_\_\_\_  
 Location Code: \_\_\_\_\_  
 Additional Information: \_\_\_\_\_

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				LH010022
0.00		Miscellaneous	Water Level					25	<input type="checkbox"/>				
3.00		Miscellaneous	Survey Abandoned						<input type="checkbox"/>				Debris
3.00		Access Point	Manhole						<input type="checkbox"/>				Debris