

Viking Pipe Services
Number: MH-050312 to MH-050311

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	6/4/99	PIPE SIZE	15" X 4'
TIME	2:07:44 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE.	LOCATION	ALONG WESTSIDE OF HILL AVE.
DWN_DESCRIPTOR	WESTSIDE OF HILL AVE.	LENGTH/RUN	400'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR,WISC.	FLOW_DIR	NORTH
TAPE_#	#2 SUPERIOR-MW-99	FLOW_RATE	LOW
COUNTER	00:52:48	DIR_MEASURED	WITH FLOW
SETUP_#	#10	ROAD_SURFACE	ASPHALT-CONC.
AREA	HILL AVE	MH_REPORT	NONE
PIPE_TYPE	RCP		
Comments	MINOR MINERAL		

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #10,THIS IS WITH THE FLOW.
19	WATER	1-2"	BOTTOM OF PIPE	
78.6	INFILTRATION AT JOINT	LIGHT		
86.7	INFILTRATION AT JOINT	LIGHT		
171.2	MINERAL AT JOINT	LIGHT		
175.2	MINERAL AT JOINT	LIGHT		
268	INFILTRATION AT JOINT	LIGHT		
340.4	TAP TO THE RIGHT	PROTRUDING 1-2"	2 O/C	
361.4	MINERAL AT JOINT	LIGHT		DEBRI ON BOTTOM OF PIPE,SMALL
385.9	CRACKED/BROKEN JOINT			
400				CENTER OF MH-050311