

PACp® Inspection Form

Surveyors Name Certificate Number System Owner Survey Customer Drainage Area Sheet No.
 Mickey Webster T-605-2280 City of Superior City of Superior District 05 1 of 1
 P/O No. Pipe Segment Reference Date Time Location (Street Name and Number) Locality (City)
 MH050312-MH050311 2008/06/16 13:53 Hill Ave / Randy Johnson ST. Superior
 Further Location Details Upstream Manhole Number Rim to Invert Grade to Invert Rim to Grade
 MH050312 MH050312
 Downstream Manhole Number Rim to Invert Grade to Invert Rim to Grade Use of Sewer Direction Flow Control Height
 MH050311 MH050311 Sanitary Downstream 15 in.
 Width Shape Material L.n. Method Joint Length Total Length Length Surveyed Year Laid Year Rehab. Tape/Media No.
 Circular Reinforced Concrete F 397.7 ft. 397.7 ft. 397.7 ft. 408
 Purpose Sewer Category Pre-Cleaning Cleaned Weather Location Code Additional Information
 Routine Assessment Not Known Dry

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole									MH050312
0.00		Miscellaneous	Water Level				10					
170.10			Infiltration	Weeper					7	2		
173.90			Infiltration	Weeper					8	4		
338.90			Tap	Break-in		6	1		2			
360.00			Infiltration	Weeper					10	2		
385.40			Infiltration	Weeper					2	5		
397.70		Access Point	Manhole									MH050311