

PACP® Inspection Form

Surveyors Name Mickey Webster	Certificate Number T-605-2280	System Owner City of Superior	Survey Customer City of Superior	Drainage Area District 05	Sheet No. 1 of 1
P/O No. MH05312A-MH050312	Pipe Segment Reference MH05312A-MH050312	Date 2008/06/16	Time 13:39	Location (Street Name and Number) Hill Ave / Randy Johnson ST.	Locality (City) Superior
Further Location Details			Upstream Manhole Number MH05312A	Rim to Invert	Grade to Invert
Downstream Manhole Number MH050312	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer Sanitary	Direction Downstream
Width Circular	Shape Circular	Material Reinforced Concrete F	Ln. Method	Joint Length 235.6 ft.	Total Length 235.6 ft.
Purpose Routine Assessment	Sewer Category	Pre-Cleaning Not Known	Cleaned	Weather Dry	Length Surveyed 235.6 ft.
Additional Information			Location Code	Year Laid	Year Rehab.
Flow Control			Flow Control	Height 15 in.	Tape/Media No. 408

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH05312A
0.00		Miscellaneous	Water Level				15		<input type="checkbox"/>				
18.90		Infiltration	Weeper						<input type="checkbox"/>	1	3		
19.70		Crack	Longitudinal						<input type="checkbox"/>	4			
44.70		Surface Damage	Reinforcement Visible						<input type="checkbox"/>	11	1		
235.60		Access Point	Manhole						<input type="checkbox"/>				MH050312