

**PACP© Inspection Form**

Surveyors Name David Sigfrids		Certificate Number U-605-2213		System Owner City of Superior		Survey Customer City of Superior		Drainage Area District 05		Sheet No. 1 of 1	
P/O No.	Pipe Segment Reference MH050314-MH050315		Date 2018/01/08	Time 10:17	Location (Street Name and Number) Hill ave		Locality (City) Superior				
Further Location Details					Upstream Manhole Number MH050315		Rim to Invert	Grade to Invert	Rim to Grade		
Downstream Manhole Number MH050314		Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer Sanitary		Direction Downstream		Flow Control	Height 15 in.	
Width	Shape Circular	Material Reinforced Concrete F	Ln. Method	Joint Length	Total Length 399.8 ft.	Length Surveyed 399.8 ft.	Year Laid	Year Rehab.	Tape/Media No. 928		
Purpose Routine Assessment		Sewer Category	Pre-Cleaning Not Known	Cleaned	Weather Dry	Location Code Light Highway	Additional Information S to N				

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	A/ From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH050315
0.00		Miscellaneous	Water Level					10	<input type="checkbox"/>				
80.20		Tap	Break-in	Intruding		4	1		<input type="checkbox"/>	10			
249.00		Deposits	Attached	Encrustation				5	<input type="checkbox"/>	7	10		
328.90		Tap	Break-in	Intruding		4	1		<input type="checkbox"/>	10			
399.80		Access Point	Manhole						<input type="checkbox"/>				MH050314