

PACP© Inspection Form

Surveyors Name David Sigfrids	Certificate Number U-605-2213	System Owner City of Superior	Survey Customer City of Superior	Drainage Area District 05	Sheet No. 1 of 1				
P/O No.	Pipe Segment Reference MH050316-MH05316A	Date 2018/01/08	Time 09:37	Location (Street Name and Number) Hill ave	Locality (City) Superior				
Further Location Details			Upstream Manhole Number MH05316A	Rim to Invert	Grade to Invert	Rim to Grade			
Downstream Manhole Number MH050316	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer Sanitary	Direction Upstream	Flow Control	Height 15 in.		
Width	Shape Circular	Material Reinforced Concrete F	Ln. Method	Joint Length	Total Length 226.4 ft.	Length Surveyed 226.4 ft.	Year Laid	Year Rehab.	Tape/Media No. 928
Purpose Routine Assessment	Sewer Category	Pre-Cleaning Not Known	Cleaned	Weather Dry	Location Code Light Highway	Additional Information N to S			

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH050316
0.00		Miscellaneous	Water Level					10	<input type="checkbox"/>				
226.40		Access Point	Manhole						<input type="checkbox"/>				MH05316A