



Inspection report

Date: 6/16/2022	Work Order:	Weather: Dry	Surveyed By: Steven Bucklin	Certificate Number: U-0819-70306510	Pipe Segment Ref.: MH05312A-MH050313
Year laid:	Pre-cleaning: Light Cleaning	Direction: Upstream	Pipe Joint Length:	Total Length:	Length Surveyed:

City: Superior	Drainage Area:	Upstream MH: MH050313
Street: HILL	Media Label: 1115	Up Rim to Invert: 0.0
Location Code: Local rural streets with light traffic	Flow Control: Lift Station	Downstream MH: MH05312A
Location Details:	Sheet Number:	Down Rim to Invert: 0.0
Pipe shape: Circular	Sewer Use: Sanitary Sewage Pipe	Total gallons used: 0.0
Pipe size: 15	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method: None	Owner: City of Superior	

Additional Info:

1:1252	Distance	Code	Observation	Counter	Photo	Grade		
MH05312A								
	0.0	AMH	Manhole / MH05312A	00:00:01	MH05312 A-MH0503 13_72cb9e			
	0.0	MWL	Water Level, 15% of the vertical dimension	00:02:23	MH05312 A-MH0503 13_19dd3			
	3.3	S01	SAP	00:03:21	MH05312 A-MH0503 13_3124c3			
	11.8	S02	DAE	00:04:28	MH05312 A-MH0503 13_f6ee5e			
	161.9	F01	SAP	00:16:12	MH05312 A-MH0503 13_7def6b	S3		
	161.9	F02	DAE	00:16:20	MH05312 A-MH0503 13_43a67	M2		
	165.8	AMH	Manhole / MH050313	00:18:53	MH05312 A-MH0503 13_de1d9			
MH050313								
QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
3E00	2E00	3E2E	96.0	60.0	156.0	3.0	2.0	2.5