

PACP® Inspection Form

Surveyors Name Mickey Webster	Certificate Number T-605-2280	System Owner City of Superior	Survey Customer City of Superior	Drainage Area District 3A	Sheet No. 1 of 1				
P/O No.	Pipe Segment Reference MH3A0306-MH3A306A	Date 2008/06/16	Time 09:12	Location (Street Name and Number) Hill Ave / 24th ST.	Locality (City) Superior				
Further Location Details			Upstream Manhole Number MH3A306A	Rim to Invert	Grade to Invert	Rim to Grade			
Downstream Manhole Number MH3A0306	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer Sanitary	Direction Downstream	Flow Control	Height 15 in.		
Width	Shape Circular	Material Reinforced Concrete F	Ln. Method	Joint Length 133.1 ft.	Total Length 133.1 ft.	Length Surveyed 133.1 ft.	Year Laid	Year Rehab.	Tape/Media No. 408
Purpose Routine Assessment	Sewer Category	Pre-Cleaning Not Known	Cleaned	Weather Dry	Location Code	Additional Information			

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Miscellaneous	Water Level					30	<input type="checkbox"/>				
0.00		Access Point	Manhole						<input type="checkbox"/>				MH3A306A
15.20		Infiltration	Weeper						<input type="checkbox"/>	8	4		
25.70		Crack	Longitudinal						<input type="checkbox"/>	12			
93.40		Infiltration	Weeper						<input type="checkbox"/>	7	9		
133.10		Access Point	Manhole						<input type="checkbox"/>				MH3A0306