

**Viking Pipe Services**  
**Number: MH-050310 to MH-03A309**

<b>FIELD</b>	<b>VALUE</b>	<b>FIELD</b>	<b>VALUE</b>
DATE	6/4/99	PIPE SIZE	15" X 4'
TIME	3:45:13 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE.	LOCATION	ALONG WESTSIDE OF HILL AVE.
DWN_DESCRIPTOR	NO. 28TH ST.	LENGTH/RUN	364'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR, WISC.	FLOW_DIR	NORTH
TAPE_#	#2 SUPERIOR-MW-99	FLOW_RATE	LOW
COUNTER	01:23:11	DIR_MEASURED	WITH FLOW
SETUP_#	#12	ROAD_SURFACE	ASPHALT-CONC.
AREA	HILL AVE	MH_REPORT	NONE
PIPE_TYPE	RCP		

Comments            MINOR MINERAL

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #12, THIS IS WITH THE FLOW.
13.6	INFILTRATION AT JOINT	LIGHT		
21.7	INFILTRATION AT JOINT	LIGHT		
54	INFILTRATION AT JOINT	LIGHT		
58	INFILTRATION AT JOINT	LIGHT		
78.2	CRACKED/BROKEN JOINT			
86.6	INFILTRATION AT JOINT	LIGHT		
102.3	INFILTRATION AT JOINT	LIGHT		
106.6	INFILTRATION AT JOINT	LIGHT		
118.5	INFILTRATION AT JOINT	LIGHT		
126.6	INFILTRATION AT JOINT	LIGHT		
148.4	TAP TO THE LEFT		10 O/C	
175.3	INFILTRATION AT JOINT	LIGHT		
195.3	INFILTRATION AT JOINT	LIGHT		
197.6				MESH SHOWING
203.4	MINERAL AT JOINT	LIGHT		
223.8	INFILTRATION AT JOINT	LIGHT		
236.2	INFILTRATION AT JOINT	LIGHT		

Viking Pipe Services  
Number: MH-050310 to MH-03A309

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
276.3	MINERAL AT JOINT	LIGHT		
293.3	TAP TO THE LEFT		10 O/C	
328.8	MINERAL AT JOINT	LIGHT		
339.6	TAP TO THE LEFT		9 O/C	
364				CENTER OF MH-03A309