

PACP® Inspection Form

| | | | | | | | | | |
|---------------------------------------|---|-----------------------------------|-------------------------------------|---|-----------------------------|------------------------------|------------------|-------------|-----------------------|
| Surveyors Name Mickey Webster | Certificate Number T-605-2280 | System Owner City of Superior | Survey Customer City of Superior | Drainage Area District 05 | Sheet No. 1 of 1 | | | | |
| P/O No. | Pipe Segment Reference MH3A0309-MH050310 | Date 2008/06/20 | Time 09:39 | Location (Street Name and Number) Hill Ave / 29th & 30th | Locality (City) Superior | | | | |
| Further Location Details | | | Upstream Manhole Number MH050310 | Rim to Invert | Grade to Invert | Rim to Grade | | | |
| Downstream Manhole Number MH3A0309 | Rim to Invert | Grade to Invert | Rim to Grade | Use of Sewer Sanitary | Direction Downstream | Flow Control | Height 15 in. | | |
| Width | Shape Circular | Material Reinforced Concrete F | Ln. Method | Joint Length 360.2 ft. | Total Length 360.2 ft. | Length Surveyed 360.2 ft. | Year Laid | Year Rehab. | Tape/Media No. 409 |
| Purpose Routine Assessment | Sewer Category | Pre-Cleaning Not Known | Cleaned | Weather Dry | Location Code | Additional Information | | | |

| Distance (Feet) | Video Ref. | Group | Description | Modifier | Cont. Defect | Inches 1st | Inches 2nd | % | Joint | At/ From | To | Image Ref. | Remarks |
|-----------------|------------|----------------|---------------------|-----------|--------------|------------|------------|----|--------------------------|----------|----|------------|----------|
| 0.00 | | Access Point | Manhole | | | | | | <input type="checkbox"/> | | | | MH050310 |
| 0.00 | | Miscellaneous | Water Level | | | | | 10 | <input type="checkbox"/> | | | | |
| 10.50 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 3 | 5 | | |
| 19.10 | | Infiltration | Dripper | | | | | | <input type="checkbox"/> | 11 | 4 | | |
| 51.40 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 8 | 4 | | |
| 80.20 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 12 | 2 | | |
| 92.30 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 3 | 5 | | |
| 92.30 | | Surface Damage | Roughness Increased | | | | | | <input type="checkbox"/> | 8 | 4 | | |
| 100.40 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 8 | 4 | | |
| 104.20 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 8 | 4 | | |
| 116.50 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 8 | 10 | | |
| 124.50 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 8 | 10 | | |
| 146.20 | | Tap | Break-in | Intruding | | 6 | 1 | | <input type="checkbox"/> | 10 | | | |
| 177.40 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 10 | 4 | | |
| 185.60 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 11 | 5 | | |
| 190.20 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 7 | 9 | | |
| 190.20 | | Surface Damage | Roughness Increased | | | | | | <input type="checkbox"/> | 10 | 4 | | |
| 193.90 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 8 | 11 | | |
| 198.30 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 2 | 5 | | |
| 201.90 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 8 | 4 | | |

| Distance (Feet) | Video Ref. | Group | Description | Modifier | Cont. Defect | Inches 1st | Inches 2nd | % | Joint | At/From | To | Image Ref. | Remarks |
|-----------------|------------|----------------|-----------------------|-----------|--------------|------------|------------|---|--------------------------|---------|----|------------|----------|
| 201.90 | | Infiltration | Weeper | | S01 | | | | <input type="checkbox"/> | 8 | 4 | | |
| 214.30 | | Surface Damage | Roughness Increased | | | | | | <input type="checkbox"/> | 11 | 1 | | |
| 257.20 | | Surface Damage | Reinforcement Visible | | | | | | <input type="checkbox"/> | 12 | 3 | | |
| 270.30 | | Surface Damage | Roughness Increased | | | | | | <input type="checkbox"/> | 9 | 12 | | |
| 281.40 | | Infiltration | Weeper | | F01 | | | | <input type="checkbox"/> | 8 | 4 | | |
| 291.40 | | Tap | Break-in | Intruding | | 6 | 1 | | <input type="checkbox"/> | 11 | | | |
| 307.30 | | Surface Damage | Roughness Increased | | | | | | <input type="checkbox"/> | 10 | 2 | | |
| 324.20 | | Surface Damage | Roughness Increased | | | | | | <input type="checkbox"/> | 9 | 3 | | |
| 327.30 | | Infiltration | Weeper | | | | | | <input type="checkbox"/> | 10 | 12 | | |
| 335.80 | | Surface Damage | Roughness Increased | | | | | | <input type="checkbox"/> | 10 | 2 | | |
| 338.00 | | Tap | Break-in | Intruding | | 6 | 1 | | <input type="checkbox"/> | 10 | | | |
| 344.40 | | Surface Damage | Roughness Increased | | | | | | <input type="checkbox"/> | 10 | 2 | | |
| 348.20 | | Surface Damage | Roughness Increased | | S02 | | | | <input type="checkbox"/> | 10 | 2 | | |
| 359.20 | | Surface Damage | Roughness Increased | | F02 | | | | <input type="checkbox"/> | 10 | 2 | | |
| 360.20 | | Access Point | Manhole | | | | | | <input type="checkbox"/> | | | | MH3A0309 |