



## Inspection report

Date: <b>6/15/2022</b>	Work Order:	Weather: <b>Dry Weather/Wet Ground</b>	Surveyed By: <b>Steven Bucklin</b>	Certificate Number: <b>U-0819-70306510</b>	Pipe Segment Ref.: <b>MH3A0309-MH050310</b>
Year laid:	Pre-cleaning: <b>Light Cleaning</b>	Direction: <b>Upstream</b>	Pipe Joint Length:	Total Length:	Length Surveyed:

City: <b>Superior</b>	Drainage Area:	Upstream MH: <b>MH050310</b>
Street: <b>HILL</b>	Media Label: <b>1115</b>	Up Rim to Invert: <b>0.0</b>
Location Code: <b>Local rural streets with light traffic</b>	Flow Control: <b>Lift Station</b>	Downstream MH: <b>MH3A0309</b>
Location Details:	Sheet Number:	Down Rim to Invert: <b>0.0</b>
Pipe shape: <b>Circular</b>	Sewer Use: <b>Sanitary Sewage Pipe</b>	Total gallons used: <b>0.0</b>
Pipe size: <b>15</b>	Sewer Category: <b>SEC</b>	Joints passed: <b>0</b>
Pipe material: <b>Reinforced Concrete Pipe</b>	Purpose: <b>Routine Assessment</b>	Joints failed: <b>0</b>
Lining Method: <b>None</b>	Owner: <b>City of Superior</b>	

Additional Info:

1:2634	Distance	Code	Observation	Counter	Photo	Grade
<b>MH3A0309</b>	0.0	AMH	Manhole / MH3A0309	00:00:01	MH3A030 9-MH0503 10_63300	
	0.0	MWL	Water Level, 10% of the vertical dimension	00:02:00	MH3A030 9-MH0503 10_77fd22	
	3.0	SRV	Surface Damage Reinforcement Visible from 9 o'clock to 2 o'clock, within 8 inch	00:02:48	MH3A030 9-MH0503 10_3de6b	S4
	5.3	S01 SAP	Surface Damage Aggregate Projecting from 9 o'clock to 3 o'clock, within 8 inch, Start	00:03:40	MH3A030 9-MH0503 10_17327	
	12.9	S02 DAE	Deposits Attached Encrustation, 5% of cross sectional area from 9 o'clock to 3 o'clock, within 8 inch, Start	00:04:51	MH3A030 9-MH0503 10_15cf32	
	22.0	B	Broken from 1 o'clock to 3 o'clock	00:06:17	MH3A030 9-MH0503 10_fc735d	S4
	22.0	SRP	Surface Damage Reinforcement Projecting from 1 o'clock to 2 o'clock	00:06:28	MH3A030 9-MH0503 10_1b211	S5
	22.0	TBA	Tap Break-in Activity at 2 o'clock, dia/height: 4inch	00:06:49	MH3A030 9-MH0503 10_cef52a	
	68.0	B	Broken from 12 o'clock to 2 o'clock, within 8 inch	00:10:13	MH3A030 9-MH0503 10_7c2b16	S4
	68.2	TB	Tap Break-in/Hammer at 1 o'clock, dia/height: 4inch, within 8 inch / CONSTANTLY RUNNING WATER.	00:10:28	MH3A030 9-MH0503 10_ffd36a	
	89.0	S03 SRV	Surface Damage Reinforcement Visible from 9 o'clock to 3 o'clock, within 8 inch, Start	00:12:33	MH3A030 9-MH0503 10_25726	
	211.5	B	Broken from 12 o'clock to 2 o'clock	00:19:56	MH3A030 9-MH0503 10_9a586	S4
	211.9	TBI	Tap Break-In Intruding at 1 o'clock, dia/height: 4inch, intruding: 2inch / CONSTANTLY RUNNING WATER.	00:20:17	MH3A030 9-MH0503 10_a5b4a	M3
	217.9	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 4 o'clock to 5 o'clock, within 8 inch	00:21:32	MH3A030 9-MH0503 10_736ee	M2
	278.5	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 4 o'clock to 5 o'clock, within 8 inch	00:25:11	MH3A030 9-MH0503 10_04a82	M2
	339.2	IDJ	Infiltration Dripper Joint from 11 o'clock to 1 o'clock, within 8 inch	00:28:34	MH3A030 9-MH0503 10_85057	M3



## Inspection report

Date: <b>6/15/2022</b>	Work Order:	Weather: <b>Dry Weather/Wet Ground</b>	Surveyed By: <b>Steven Bucklin</b>	Certificate Number: <b>U-0819-70306510</b>	Pipe Segment Ref.: <b>MH3A0309-MH050310</b>
Year laid:	Pre-cleaning: <b>Light Cleaning</b>	Direction: <b>Upstream</b>	Pipe Joint Length:	Total Length:	Length Surveyed:

1:2634	Distance	Code	Observation	Counter	Photo	Grade	
	358.8	OBN	Obstruction Construction Debris, 5% of cross sectional area from 5 o'clock to 7 o'clock, within 8 inch	00:30:05	MH3A030 9-MH0503 10_53ae6	M2	
	358.8	F01	SAP	Surface Damage Aggregate Projecting from 9 o'clock to 3 o'clock, within 8 inch, Finish	00:30:17	MH3A030 9-MH0503 10_b3c987	S3
	358.8	F02	DAE	Deposits Attached Encrustation, 5% of cross sectional area from 9 o'clock to 3 o'clock, within 8 inch, Finish	00:30:26	MH3A030 9-MH0503 10_6f6763	M2
	358.8	F03	SRV	Surface Damage Reinforcement Visible from 9 o'clock to 3 o'clock, within 8 inch, Finish	00:30:34	MH3A030 9-MH0503 10_192c97	S4
	363.2	AMH	Manhole / MH050310	00:33:04	MH3A030 9-MH0503 10_25323		

  

QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
514J	322M	514J	450.0	150.0	600.0	3.5	2.0	2.9