

tape # 110 MFR TDK R1 Staw.  
 MODEL T-120  
 Ex 200 St.

O3A 306 - O3A 307 21" ACP 36"  
 quality good

counter 0 - 2-26-91

Fair condition

- 0 - upstream MH. O3A 307. Flow 1/3 pipe.
- 08' Left side 10 o'clock light mineral deposits.
- 93' right side 2 o'clock. light mineral deposits.  
+ light roots
- 139' left side 10 o'clock. light root & <sup>light</sup> mineral  
~~deposits~~ deposits
- 142' left side 9 o'clock. <sup>light</sup> mineral deposit.
- 160' camera becoming submerged Flow 1/3 pipe
- 173' camera 1/2 way submerged Flow 1/3 pipe.
- 200' camera going up ~~down~~ above water over  
joints. Flow 1/3 pipe
- 208 right side 3 o'clock light mineral deposits.
- 235' camera above water. Flow 1/3 pipe
- 240' camera becoming submerged Flow 1/3 pipe  
camera going up & down over joints.
- 255' camera totally submerged
- 278' <sup>very</sup> camera going up & down over joints. still  
submerged. (Totally)
- 325' camera 3/4 submerged Flow 1/3 pipe
- 335' camera totally submerged
- 367' downstream MH. O3A 306 camera totally  
submerged unable to determine flow.

~~the~~ joints ~~seem~~ seem to have  
 very light mineral deposits  
 & some are a little rough.

counter 835