

WinCan

Absolute Pipe PO Box 943, Newton, IA Tel. 515-966-5887 steven@absolutepipe.com

			Inspec	tion re	port				
Date: Work Order: 6/15/2022 Year laid: Pre-cleaning Heavy Cleani		re-cleaning:	Light Rain Steven Bucklin U-0819-70			Certificate N U-0819-703 Total Len	306510 MH3A307A-MH3A3080		
City: Street: Location Code: Location Details: Pipe shape: Pipe size: Pipe material: Lining Method: Additional Info:	Superior HILL Local rural streets with light traffic Circular 15 Reinforced Concrete Pipe None		Media Label: 1115 Flow Control: Lift Station Sheet Number: Sewer Use: Sewer Use: Sanitary Sewage Pipe Sewer Category: SEC		Upstream MH: Up Rim to Invert: Downstream MH: Down Rim to Invert: Total gallons used: Joints passed: Joints failed:		MH3A308C 0.0 MH3A307A 0.0 0.0 0 0		
1:541	Distance	Code	Observation				Counter	Photo	Grade
MH3A307A									
	0.0	AMH	Manhole / MH3A	307A			00:00:01	MH3A307 A-MH3A30 8C_e6646	
	0.0	MWL	Water Level, 10%	6 of the vert	cal dimension		00:01:56	MH3A307 A-MH3A30 8C_703c7f	
	6.6	S01 DAE	Deposits Attache from 9 o'clock to				00:03:07		
	6.6	S02 SAP	Surface Damage o'clock, within 8 i		Projecting from	9 o'clock to 3	00:03:47	MH3A307 A-MH3A30 8C_779f10	
	13.6	SRP	Surface Damage to 3 o'clock, withi		ent Projecting fr	rom 9 o'clock	00:05:10	MH3A307 A-MH3A30 8C_6f7ede	S 5
	19.3	В	Broken from 12 c	clock to 2 c	'clock		00:06:11	MH3A307 A-MH3A30 8C 894d8	S4
†	20.0	TBI	Tap Break-In Intr intruding: 1inch	uding at 1 o	clock, dia/heigh	t: 4inch,	00:06:26	MH3A307 A-MH3A30 8C_f70ba1	M2
	68.4	F01 DAE F02 SAP	Deposits Attache from 9 o'clock to Surface Damage	3 o'clock, w	thin 8 inch, Finis	sh		MH3A307 A-MH3A30 8C_6a061 MH3A307	M2 \$3
	71.7	AMH	o'clock, within 8 i	nch, Finish	rojeoung nolli			A-MH3A30 8C_a41c2 MH3A307 A-MH3A30	00
								8C_bf3297	
MH3A308C	QMR	QOR	SPR	MPR	OPR	SPRI	MP		OPRI

City_of_Superior_Hill_Interceptor // Page: 10