

Viking Pipe Services

Number: MH-03A309 to MH-03A308A

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	6/8/99	PIPE SIZE	15" X 4'
TIME	4:42:13 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE	LOCATION	RUNS DOWN
DWN_DESCRIPTOR	WESTSIDE OF HILL AVE		WESTSIDE OF HILL AVE
JOB_#	17-99	LENGTH/RUN	133'
CLIENT	SUPERIOR, WISC.	INSPECTOR	MW
TAPE_#	#4 SUPERIOR-MW-99	FLOW_DIR	NORTH
COUNTER	01:26:40	FLOW_RATE	LOW
SETUP_#	#13	DIP_MEASURED	WITH FLOW
AREA	HILL AVE	ROAD_SURFACE	ASPHALT-CONC.
PIPE_TYPE	ROP	MH_REPORT	NONE

Comments MINOR MINERAL & INFIL.

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0.				START OF RUN #13, THIS IS WITH THE FLOW
26.6	INFILTRATION AT JOINT	LIGHT		
42.7	MINERAL AT JOINT	LIGHT		
63.1	INFILTRATION AT JOINT	LIGHT		
133				CENTER OF MH-03A308A