

PACP® Inspection Form

Surveyors Name Mickey Webster		Certificate Number T-605-2280		System Owner City of Superior		Survey Customer City of Superior		Drainage Area District 3A		Sheet No. 1 of 1	
P/O No.	Pipe Segment Reference MH3A308A-MH3A0309		Date 2008/06/20	Time 11:45	Location (Street Name and Number) Hill Ave / 27th & 28th			Locality (City) Superior			
Further Location Details					Upstream Manhole Number MH3A308A		Rim to Invert	Grade to Invert	Rim to Grade		
Downstream Manhole Number MH3A0309		Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer Sanitary		Direction Upstream	Flow Control	Height 15 in.		
Width	Shape Circular	Material Reinforced Concrete F	Ln. Method	Joint Length 130 ft.	Total Length 130 ft.	Length Surveyed 130 ft.	Year Laid	Year Rehab.	Tape/Media No. 409		
Purpose Routine Assessment		Sewer Category	Pre-Cleaning Not Known	Cleaned	Weather Dry	Location Code	Additional Information				

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH3A308A
0.00		Miscellaneous	Water Level					10	<input type="checkbox"/>				
61.10		Surface Damage	Reinforcement Visible						<input type="checkbox"/>	1	4		
108.00		Crack	Longitudinal						<input type="checkbox"/>	12			
130.00		Access Point	Manhole						<input type="checkbox"/>				MH3A0309