

PACP© Inspection Form

Surveyors Name Mickey Webster Certificate Number T-605-2280 System Owner City of Superior Survey Customer City of Superior Drainage Area District 3A Sheet No. 1 of 1
 P/O No. MH3A308C-MH3A308A Pipe Segment Reference MH3A308C-MH3A308A Date 2008/06/16 Time 12:47 Location (Street Name and Number) Hill Ave / 25th / 26th Locality (City) Superior
 Further Location Details MH3A308C Upstream Manhole Number MH3A308C Rim to Invert Grade to Invert Rim to Grade
 Downstream Manhole Number MH3A308A Rim to Invert Grade to Invert Rim to Grade Use of Sewer Sanitary Direction Upstream Flow Control Height 15 in.
 Width Shape Circular Material Reinforced Concrete F Ln. Method Joint Length 96.8 ft. Total Length 96.8 ft. Length Surveyed 96.8 ft. Year Laid Year Rehab. Tape/Media No. 408
 Purpose Routine Assessment Sewer Category Pre-Cleaning Not Known Cleaned Weather Dry Location Code Additional Information

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						<input type="checkbox"/>				MH3A308C
0.00		Miscellaneous	Water Level				25		<input type="checkbox"/>				
56.90		Infiltration	Weeper						<input type="checkbox"/>	10	2		
76.90		Infiltration	Weeper						<input type="checkbox"/>	9	3		
85.70		Infiltration	Weeper						<input type="checkbox"/>	2	5		
89.80		Infiltration	Weeper						<input type="checkbox"/>	3	5		
96.80		Miscellaneous	Survey Abandoned						<input type="checkbox"/>				Water Level High
96.80		Access Point	Manhole						<input type="checkbox"/>				Water Level High