

PACP® Inspection Form

Surveyors Name Mickey Webster	Certificate Number T-605-2280	System Owner City of Superior	Survey Customer 	Drainage Area District 06	Sheet No. 1 of 1
P/O No. 	Pipe Segment Reference MH060111-MH060112	Date 2007/09/13	Time 13:05	Location (Street Name and Number) St. Albans Dr.	Locality (City) Superior
Further Location Details 		Upstream Manhole Number MH060111	Rim to Invert 	Grade to Invert 	Rim to Grade
Downstream Manhole Number MH060112	Rim to Invert 	Grade to Invert 	Rim to Grade 	Use of Sewer Sanitary	Direction Upstream
Flow Control 		Height 12 in.			
Width 	Shape Circular	Material Clay Tile	Ln. Method 	Joint Length 23.4 ft.	Total Length 23.4 ft.
Length Surveyed 23.4 ft.		Year Laid 	Year Rehab. 	Tape/Media No. 376	
Purpose Routine Assessment	Sewer Category 	Pre-Cleaning Not Known	Cleaned 	Weather Dry	Location Code
Additional Information 					

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At/ From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						☐				MH060111
0.00		Miscellaneous	Water Level					10	☐				
6.40		Crack	Longitudinal						☐	12			
6.50		Crack	Spiral						☐	11	2		
10.50		Crack	Multiple						☐	10	3		
15.20		Crack	Multiple		S01				☐	9	3		
17.40		Miscellaneous	Material Change						☐				Clay Tile / PVC
18.40		Tap	Factory Made			6			☐	10			
23.40		Miscellaneous	Survey Abandoned						☐				Offset between PVC / Clay tile
23.40		Crack	Multiple		F01				☐	9	3		
23.40		Access Point	Manhole						☐				Offset Pipe