

PACP® Inspection Form

Surveyors Name Mickey Webster	Certificate Number T-605-2280	System Owner City of Superior	Survey Customer City of Superior	Drainage Area District 06	Sheet No. 1 of 1
P/O No. MH060111-MH060112	Pipe Segment Reference MH060111-MH060112	Date 2007/08/06	Time 13:26	Location (Street Name and Number) St. Albans Rd	Locality (City) Superior
Further Location Details MH060112			Upstream Manhole Number MH060111		
Downstream Manhole Number MH060112	Rim to Invert 	Grade to Invert 	Rim to Grade 	Use of Sewer Sanitary	Direction Upstream
Width Circular	Material Clay Tile	Ln. Method 	Joint Length 20.6 ft.	Total Length 20.6 ft.	Length Surveyed 20.6 ft.
Purpose Routine Assessment	Sewer Category 	Pre-Cleaning Not Known	Cleaned 	Weather Dry	Location Code
Additional Information 					

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	Inches 1st	Inches 2nd	%	Joint	At From	To	Image Ref.	Remarks
0.00		Access Point	Manhole						☐				MH060111
0.00		Miscellaneous	Water Level				10		☐				
5.10		Crack	Multiple						☐	11	2		
6.10		Crack	Longitudinal						☐	12			
10.90		Crack	Multiple						☐	11	2		
10.90		Infiltration	Weeper						☐	12	1		
12.20		Crack	Multiple						☐	8	4		
13.60		Crack	Multiple		S01				☐	8	4		
16.80		Miscellaneous	Material Change						☐				PVC
18.80		Tap	Factory Made		6				☐	10			
20.60		Miscellaneous	Survey Abandoned						☐				Debris in Line
20.60		Crack	Multiple		F01				☐	8	4		
20.60		Access Point	Manhole						☐				Debris in Line