



Stack Bros.
3119 Hill Ave. Superior WI

Tel: 7153982964

Fax:

E-mail:

Inspection Report

MH06112A-MH060113

Date 4/25/2019	P/O. No.	Weather Dry	Surveyor's Name Josh Gordon	Pipe Segment Reference ~~MH060113~~ - ~~MH06112A~~	Section No. 7
Certificate No. U-215-06023623	Survey Customer	System Owner	Preset :	Pre-Cleaning No Pre-Cleaning	Sewer Category

Street SW of Newton & St. Albans	Use of Sewer Combined	Upstream MH MH060113
City City of Superior	Drainage Area District 6	Dowstream MH MH06112A
Loc. details Light Highway	Flow Control	Dir. of Survey Downstream
Location Code	Length surveyed 20.37 ft	Section Length 20.37 ft

Purpose of Survey Maintenance Related	Joint Length	8 inch
Year Laid	Dia./Height	Vitrified Clay Pipe
Year Rehabilitated 1000	Material	
Tape / Media No. 979	Lining Method	

Add. Information :

1:56	Position	Code	Observation	Photo	Grade		
MH060113 0.00 0.00 0.00 0.00 0.00 2.10 2.10 4.56 6.99 9.55 20.37 S1	AMH	Manhole, MH060113 / MH060113					
	MWL	Water Level, 5 % of cross sectional area					
	B	Broken, from 11 o'clock, to 2 o'clock, within 8 inch					
	RMB	Roots Medium Barrell, at 11 o'clock, 5 % lost, within 8 inch					
	RMB	Roots Medium Barrell, at 2 o'clock, 5 % lost, within 8 inch					
	CH3	Crack Longitudinal Hinge, 3, at 12 o'clock, within 8 inch					
	RMJ	Roots Medium Joint, from 7 o'clock, to 4 o'clock, 10 % lost, within 8 inch					
	RMJ	Roots Medium Joint, from 7 o'clock, to 4 o'clock, 15 % lost, within 8 inch, Start					
	DNF	Deposits Ingress Fine, 10 % of cross sectional area, at 7 o'clock, within 8 inch					
	DNF	Deposits Ingress Fine, 10 % of cross sectional area, at 5 o'clock, within 8 inch					
	MSA	Survey Abandoned, water level and settled deposits / water level and settled deposits					
QSR	QMR	SPR	MPR	OPR	SPRI	MPRI	OPRI