

VIKING PIPE SERVICES
BEMIDJI, MINN.
2000

JOB # : 17-99
CLIENT : SUPERIOR, WISC.

LOG REPORT
02-07-80

(193)
TAPE : #191-00 SUPERIOR-DH
COUNTER : 00:41:01-00:44:18
SETUP/AREA : 05 / DIST.6
PIPE SIZE : 08" X 06'
PIPE TYPE : VCP
JOINT TYPE : BELL/GASKET
LOCATION : GARFIELD-BE-
WEEN BELKNAP & WINTER ST.

U/STREAM : HEADING EAST
HEADING EAST
D/STREAM MH: 060005E
ARROWHEAD VAN&STORAGE BLDG
FLOW/DIR. : LOW/WEST
DIR./MEA. : AGAINST/FLOW
ROADWAY : GRAV. /GRAV.
LINE # : HEAD.E. -060005E

LENGTH/RUN : B/O @ 6'.
INSPECTOR : D. HARMS
" INSPECTOR'S COMMENTS "
B/O DUE TO OILY SLUDGE, DE-
BRIS & H2O IN THE LINE AT
THIS TIME.
-TOTAL LENGTH NOT KNOWN
-REVERSE NOT POSSIBLE HERE

FOOTAGE:

4.0 Ft

6.0 Ft

FAULT OR COMMENTS:

START OF RUN #05, AND THIS
IS AGAINST THE FLOW.
STARTING OUT IN 5-6" OILY
SLUDGE, DEBRIS & H2O-

B/O @ 6', DUE TO OILY
SLUDGE, DEBRIS & H2O IN
LINE AT THIS TIME.
-TOTAL LENGTH NOT KNOWN-
-REVERSE NOT POSSIBLE-