

**Viking Pipe Services**  
**Number: MH-020437G to MH-060001**

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	7/28/99	PIPE SIZE	15" X 4'
TIME	1:27:20 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPT	EAST CENTER OF TRAIN YARD	LOCATION	ACROSS TRAIN YARD SOUTHSIDE OF BRIDGE
DWN_DESCRIPT	BY SUPER ONE FOODS	LENGTH/RUN	271'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR,WISC.	FLOW_DIR	EAST
TAPE_#	#6-99 SUPERIOR-MW	FLOW_RATE	LOW
COUNTER	01:17:23	DIR_MEASURED	AGAINST FLOW
SETUP_#	#08	ROAD_SURFACE	ASPHALT-CONC.
AREA	#06	MH_REPORT	NONE
PIPE_TYPE	RCP		

Comments            FEW SAGS

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
7	DIRT	0-1"	BOTTOM OF PIPE	START OF RUN #08, THIS IS AGAINST THE FLOW.
16.6	SAG	START OF		
24.7	CRACKED/BROKEN JOINT			
88.5	SAG	END OF		
100				FEW SAGS
271				CENTER OF MH-060001