

Viking Pipe Services
Number: MH-050312A to MH-050312

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	6/4/99	PIPE SIZE	15" X 4'
TIME	1:44:37 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE.	LOCATION	ALONG WESTSIDE OF HILL AVE.
DWN_DESCRIPTOR	WESTSIDE OF HILL AVE.	LENGTH/RUN	236'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR,WISC.	FLOW_DIR	NORTH
TAPE_#	#2 SUPERIOR-MW-99	FLOW_RATE	LOW
COUNTER	00:45:26	DIR_MEASURED	WITH FLOW
SETUP_#	#09	ROAD_SURFACE	ASPHALT-CONC.
AREA	HILL AVE	MH_REPORT	SEE ATTACHED
PIPE_TYPE	RCP		
Comments	MINOR MINERAL		

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #09,THIS IS WITH THE FLOW
10	WATER	2-4"	BOTTOM OF PIPE	
20.2	MINERAL AT JOINT	LIGHT		
33.4	DEBRI	SMALL	BOTTOM OF PIPE	
60.6	MINERAL AT JOINT	LIGHT		
92.2	DEBRI	SMALL	BOTTOM OF PIPE	
144.9	MINERAL AT JOINT	LIGHT		
236				CENTER OF MH-050311