

Viking Pipe Services
Number: MH-050315 to MH-050314

FIELD	VALUE	FIELD	VALUE
DATE	6/4/99	PIPE SIZE	15" X 4'
TIME	11:07:42 AM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE.	LOCATION	ALONG WESTSIDE OF HILL AVE.
DWN_DESCRIPTOR	WESTSIDE OF HILL AVE.	LENGTH/RUN	400'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR,WISC.	FLOW_DIR	NORTH
TAPE_#	#2 SUPERIOR-MW-99	FLOW_RATE	LOW
COUNTER	00:12:49	DIR_MEASURED	WITH FLOW
SETUP_#	#06	ROAD_SURFACE	ASPHALT-CONC.
AREA	HILL AVE	MH_REPORT	SEE ATTACHED
PIPE_TYPE	RCP		
Comments	MINOR MINERAL		

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
7				START OF RUN #06,THIS IS WITH THE FLOW
9	WATER	1-2"	BOTTOM OF PIPE	
80.9	TAP TO THE LEFT		9 O/C	
181	DEBRI	SMALL		
197	CRACKED/BROKEN JOINT			
228.7	MINERAL AT JOINT	LIGHT		
248.9	MINERAL AT JOINT	LIGHT		
317.8	MINERAL AT JOINT	LIGHT		
328.3	TAP TO THE LEFT		9 O/C	
341.8	MINERAL AT JOINT	LIGHT		
374.1	MINERAL AT JOINT	LIGHT		
382.1	MINERAL AT JOINT	LIGHT		
400				CENTER OF MH-050314